

General Information

Date & Time: 24, Oct, 2025 09:22

Make	Toyota	Model	Corolla Altis
YOM	2010	Odo Meter Reading	97,425
Registration No.	NWQ304	Chassis No.	MR053ZEE106159252
CC	1.6	Transmission	M/T
Fuel Type	Gas	Type of Body	Sedan
Colour	Silver		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	128.3	127	130	128
2	Boot Lid	115.0	109	127	109
3	Roof	105.5	109	109	107/97
4	Left Front Fender	115.6	114	117	116
5	Left Front Door	123.0	130	125	114
6	Center Panel Left				
7	Left Rear Door	109.6	113	113	103
8	Left Back Panel	115.3	106	111	129
9	Right Front Fender	109.6	113	112	104
10	Right Front Door	120.0	113	124	123
11	Center Panel Right				
12	Right Rear Door	102.9	94	106	109
13	Right Back Panel	115.3	124	110	112

Overall Evaluation :

D

Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

Interior Evaluation : D	Exterior Evaluation : E
 <p>a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain</p>	 <p>A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap</p>
<p>Remarks Ceiling - Grime - Small / Mat Other - Missing - Yes / Sunvisor, Sunglass Holder - Grime - Medium / (R) Front Trim - Grime - Small / Overall Interior - Worn as per age - Yes / (R) Front Seat - Grime - Medium / Rear Seat - Grime - Large / (L) Rear Trim - Grime - Small / (L) Front Trim - Grime - Medium / (L) Front Seat - Grime - Medium / Steering Wheel - Worn, Peel, Crack - Small / Dashboard - Worn, Scratch, Cut, Crack - Large</p>	<p>Remarks Front Bumper, Grille, Lamps - Scratch & Dent - Large / (R) Front Fender, Molding - Scratch - Small / (R) Mirror - Scratch - Small / (R) Front Door, Molding - Scratch - Small / (R) Rear Door, Molding - Scratch & Dent - Medium / (R) Rear Fender, Molding - Scratch - Small / Rear Bumper, Lamps, Panels - Scratch & Dent - Medium / (L) Rear Fender, Molding - Scratch - Small / (L) Rear Door, Molding - Scratch - Small / (L) Front Door, Molding - Scratch - Small / (L) Front Fender, Molding - Scratch - Small / (L) Mirror - Scratch - Small / Roof - Scratch & Dent - Small / Bonnet, Headlight - Scratch - Small / Trunk Hood, Rear Gate - Scratch - Small</p>
Frame Evaluation : A	Functional Evaluation : D
<p>Remarks Defects not found</p>	<p>Remarks Power Steering - Issue - Yes / Battery - Weak - Yes / Audio, Radio - Issue - Yes / Reverse Camera - N/A - Yes / Parking Brake - Function - Weak / Brake Pedal - Function - Weak / Spare Key - Issue - Unexist</p>

<p>Inspector Notes</p>
<p>Worn as per age. Radio issue. Brake pedal issue. Without warranty booklet,jack,tools and seat cover. with spare tire. 1 key no remote. With LTO plate.</p>