

General Information

Date & Time: 23, Oct, 2025 15:55

Make	Toyota	Model	Avanza
YOM	2025	Odo Meter Reading	30,661
Registration No.	CCG4162	Chassis No.	MHFAA1BY2R0029527
CC	1.3	Transmission	CVT
Fuel Type	Gas	Type of Body	MPV
Colour	Black		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	108.6	107	107	112
2	Boot Lid	105.0	101	114	100
3	Roof	108.6	109	111	115/100
4	Left Front Fender	95.3	97	92	97
5	Left Front Door	110.6	100	109	123
6	Center Panel Left				
7	Left Rear Door	108.6	114	102	110
8	Left Back Panel	99.4	108	97	93
9	Right Front Fender	97.3	101	100	91
10	Right Front Door	107.1	113	110	98
11	Center Panel Right				
12	Right Rear Door	108.0	115	101	108
13	Right Back Panel	115.3	107	117	122

Overall Evaluation :

A

Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

Interior Evaluation : A	Exterior Evaluation : B
 <p>a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain</p>	 <p>A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap</p>
<p>Remarks Ceiling - Grime - Small / (L) Front Floor Mat - Worked - Small</p>	<p>Remarks Front Bumper, Grille, Lamps - Scratch - Medium / (L) Front Fender, Molding - Dent - Minimal / (L) Mirror - Scratch - Minimal / (L) Front Door, Molding - Scratch - Minimal / (L) Rear Door, Molding - Scratch & Dent - Minimal / (L) Step, In-panel, Side Spoiler - Scratch & Dent - Minimal / Bonnet, Headlight - Scratch - Minimal / Roof - Scratch & Dent - Minimal / (R) Front Fender, Molding - Scratch - Minimal / (R) Front Door, Molding - Scratch & Dent - Minimal / (R) Rear Door, Molding - Scratch - Minimal / (R) Rear Fender, Molding - Scratch - Minimal / (L) Rear Fender, Molding - Scratch - Minimal / Trunk Hood, Rear Gate - Scratch & Dent - Minimal / Rear Bumper, Lamps, Panels - Scratch - Small</p>
Frame Evaluation : A	Functional Evaluation : A
<p>Remarks Defects not found</p>	<p>Remarks Defects not found</p>

<p>Inspector Notes</p>
<p>With LTO plate and Sparetire, No Tools and Jack and Warranty booklet, scratch headlight and tail light.</p>