

General Information

Date & Time: 27, Oct, 2025 15:02

Make	Ford	Model	Everest
YOM	2012	Odo Meter Reading	125,956
Registration No.	UIZ578	Chassis No.	MNCUS4D10CW402156
CC	2.2	Transmission	A/T
Fuel Type	Diesel	Type of Body	Wagon
Colour	White		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	93.4	87	108	86
2	Boot Lid	77.8	70	88	77
3	Roof	79.6	80	66	93/80
4	Left Front Fender	88.1	87	85	92
5	Left Front Door	94.9	103	93	89
6	Center Panel Left				
7	Left Rear Door	90.0	86	89	96
8	Left Back Panel	88.5	81	94	91
9	Right Front Fender	85.9	95	78	85
10	Right Front Door	99.0	94	99	104
11	Center Panel Right				
12	Right Rear Door	96.5	101	100	89
13	Right Back Panel	142.8	159	183	87

Overall Evaluation :

C

Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

Interior Evaluation : C	Exterior Evaluation : D
 <p>a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain</p>	 <p>A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap</p>
<p>Remarks Overall Interior - Worn as per age - Yes / Rear Seat - Worn - Yes / (R) Front Seat - Worn - Yes / (L) Front Seat - Worn - Yes / (L) Front Trim - Grime - Minimal / Ceiling - Grime - Small / Trunk Room - Worn, Scratch, Cut, Crack - Medium</p>	<p>Remarks (R) Rear Fender - Repair Traces - Yes / (R) Mirror - Stuck - Yes / (R) Front Fender, Molding - Scratch - Small / (R) Step, In-panel, Side Spoiler - Scratch - Small / (R) Front Door, Molding - Scratch - Minimal / Overall Exterior - Faded(Color, Gloss) - Yes / Overall Exterior - Worn as per age - Yes / (R) Rear Door, Molding - Scratch - Minimal / (R) Rear Fender, Molding - Scratch - Minimal / Rear Bumper, Lamps, Panels - Scratch - Medium / Trunk Hood, Rear Gate - Scratch - Medium / (L) Rear Fender, Molding - Scratch - Small / (L) Rear Door, Molding - Scratch - Medium / (L) Front Door, Molding - Scratch - Small / (R) Mirror - Scratch - Minimal / (L) Mirror - Scratch - Minimal / (L) Front Fender, Molding - Scratch - Minimal / Front Bumper, Grille, Lamps - Scratch - Medium / Bonnet, Headlight - Scratch & Dent - Medium / Roof - Rust, Corrosion - Small / Front Windshield - Scratch, Stone chip - Small</p>
Frame Evaluation : A	Functional Evaluation : B
<p>Remarks Defects not found</p>	<p>Remarks Retractable Mirror - Issue - Yes / Reverse Camera - N/A - Yes / Spare Key - Issue - Unexist</p>

<p>Inspector Notes</p>
<p>with warranty booklet, with jack and tools, with spare tire, with LTO plate, scratches on headlight and tail light, yellowish headlight, O/D INDICATOR LIGHT ON</p>