

General Information

Date & Time: 17, Dec, 2024 10:56

Make	Toyota	Model	Veloz
YOM	2023	Mileage	20,606
Registration No.	EAG5111	Chassis No.	MHFAB1BY7P3063925
CC	1.5	Transmission	CVT
Fuel Type	Gas	Type of Body	SUV
Colour	Red		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	83.4	89	74	88
2	Boot Lid	93.1	89	108	83
3	Roof	100.7	107	106	91/99
4	Left Front Fender	168.6	172	173	161
5	Left Front Door	100.6	98	93	111
6	Center Panel Left				
7	Left Rear Door	97.6	114	89	90
8	Left Back Panel	119.2	137	96	125
9	Right Front Fender	167.6	181	165	157
10	Right Front Door	156.6	167	150	153
11	Center Panel Right				
12	Right Rear Door	111.0	121	100	112
13	Right Back Panel	117.6	125	106	122

Overall Evaluation :

A

Disclaimer

This Grading Report is intended to record the general appearance and condition of the interior, exterior & frame of the vehicle. This is not a detailed inspection report. This is issued on the date and time given herein and the company shall not be liable for the condition of the vehicle after this date and time. Any disputes regarding this report shall not be grounds for arbitration.

Interior Evaluation : A	Exterior Evaluation : A
 a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain	 A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap
Remarks Defects not found	Remarks (R) Front Fender - Repair Traces - Yes
Frame Evaluation : A	Functional Evaluation : A
Remarks Defects not found	Remarks Defects not found

Inspector Notes
with spare tire/No warranty booklet/tools and jack