

General Information

Date & Time: 25, Oct, 2025 07:24

Make	Toyota	Model	Vios
YOM	2025	Odo Meter Reading	26,004
Registration No.	CCK2299	Chassis No.	PA1B18F38R42758535
CC	1.3	Transmission	CVT
Fuel Type	Gas	Type of Body	Sedan
Colour	Blackish Red Mica		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	116.6	115	112	123
2	Boot Lid	102.0	101	94	111
3	Roof	83.2	88	87	72/86
4	Left Front Fender	90.7	90	91	91
5	Left Front Door	92.5	93	92	93
6	Center Panel Left				
7	Left Rear Door	132.6	138	129	131
8	Left Back Panel	98.7	103	103	90
9	Right Front Fender	96.9	91	100	100
10	Right Front Door	100.1	95	98	107
11	Center Panel Right				
12	Right Rear Door	116.3	115	114	120
13	Right Back Panel	96.1	96	96	97

Overall Evaluation :

B

Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

Interior Evaluation : C	Exterior Evaluation : B
 <p>a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain</p>	 <p>A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap</p>
<p>Remarks (L) Front Floor Mat - Worked - Large / (R) Front Floor Mat - Grime - Small / Mat Other - Grime - Small</p>	<p>Remarks Front Bumper, Grille, Lamps - Scratch - Medium / (L) Front Fender, Molding - Scratch - Minimal / (L) Front Door, Molding - Scratch & Dent - Minimal / (L) Rear Door, Molding - Scratch - Small / Member (Bolted) - Dent - Yes / Bonnet, Headlight - Scratch - Small / (R) Front Door, Molding - Scratch - Small / (R) Rear Door, Molding - Scratch - Minimal / (R) Rear Fender, Molding - Scratch - Minimal / Trunk Hood, Rear Gate - Scratch - Minimal / Rear Bumper, Lamps, Panels - Scratch - Minimal / (L) Rear Fender, Molding - Scratch - Minimal / Roof - Scratch - Small / (R) Mirror - Scratch - Minimal</p>
Frame Evaluation : A	Functional Evaluation : A
<p>Remarks Defects not found</p>	<p>Remarks Defects not found</p>

<p>Inspector Notes</p>
<p>With LTO plate and Sparetire and Jack and Incomplete Tools and warranty booklet, scratch headlight and tail light, Worn Tires, foul smell.</p>