

## General Information

Date & Time: 27, Oct, 2025 17:56

<b>Make</b>	Volkswagen	<b>Model</b>	Touran
<b>YOM</b>	2014	<b>Odo Meter Reading</b>	70,980
<b>Registration No.</b>	AOA8586	<b>Chassis No.</b>	WVGZZZ1TZEW017040
<b>CC</b>	2.0	<b>Transmission</b>	A/T
<b>Fuel Type</b>	Diesel	<b>Type of Body</b>	MPV
<b>Colour</b>	Silver		

## Body / Panel Condition



#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	520.0	198	1,110	252
2	Boot Lid	191.6	191	176	208
3	Roof	139.7	118	126	163/152
4	Left Front Fender	223.6	233	204	234
5	Left Front Door	242.3	240	256	231
6	Center Panel Left				
7	Left Rear Door	227.0	214	221	246
8	Left Back Panel	217.6	219	215	219
9	Right Front Fender	235.6	254	236	217
10	Right Front Door	231.6	217	222	256
11	Center Panel Right				
12	Right Rear Door	232.0	215	235	246
13	Right Back Panel	238.0	238	232	244

## Overall Evaluation :

**E**

### Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

<b>Interior Evaluation :</b> <span style="float: right;"><b>E</b></span>	<b>Exterior Evaluation :</b> <span style="float: right;"><b>E</b></span>
<p><b>a</b> : Cut, Fray <b>d</b> : Loose, Deformed <b>k</b> : Animal Hair <b>s</b> : Smell <b>t</b> : Cigarette Burns <b>x</b> : Defective <b>y</b> : Stain</p>	<p><b>A</b> : Scratch <b>AU</b> : Scratch &amp; Dent <b>B</b> : Modified <b>C</b> : Corrosion <b>G</b> : Stone chip <b>P</b> : Faded <b>S</b> : Rust <b>SC</b> : Rust &amp; Corrosion <b>U</b> : Dent <b>X</b> : Defective <b>Y</b> : Crack, Gap</p>
<b>Remarks</b> Overall Interior - Worn as per age - Yes / Overall Interior - Smell - Yes / Mat Other - Grime - Small / Dashboard - Worn, Scratch, Cut, Crack - Small / Glove Box - Worn, Scratch, Cut, Crack - Small / Instrument Panel - Worn, Scratch, Cut, Crack - Small / Steering Wheel - Worn, Peel, Crack - Small / Console, Switches, Vents - Worn, Scratch, Cut, Crack - Small / Room Mirror - Stuck - Yes / Sunvisor, Sunglass Holder - Worked - Small / Sunvisor, Sunglass Holder - Loose, Deformed - Small / (L) Front Seat - Worn - Yes / (R) Front Seat - Worn - Yes / (L) Front Trim - Loose, Deformed - Small / (R) Front Trim - Loose, Deformed - Small / (R) Rear Trim - Loose, Deformed - Small / (L) Rear Trim - Loose, Deformed - Small / Rear Seat - Worn - Yes / Dashboard - Traces of Adhesive Tape - Yes	<b>Remarks</b> (R) Front Door - Repair Traces - Yes / (R) Step - Repair Traces - Yes / (R) Front Fender - Repair Traces - Yes / Bonnet - Repair Traces - Yes / (L) Front Fender - Repair Traces - Yes / (L) Front Door - Repair Traces - Yes / (L) Step - Repair Traces - Yes / (L) Rear Door - Repair Traces - Yes / (L) Rear Fender - Repair Traces - Yes / Trunk Hood, Rear Gate - Repair Traces - Yes / Rear End Panel - Repair Traces - Yes / (R) Rear Fender - Repair Traces - Yes / (R) Rear Door - Repair Traces - Yes / Roof - Repair Traces - Yes / Roof - Repair mark - Yes / Trunk Hood, Rear Gate - Repair mark - Yes / (L) Rear Fender, Molding - Repair mark - Yes / (L) Rear Door, Molding - Repair mark - Yes / (L) Front Door, Molding - Repair mark - Yes / (L) Front Fender, Molding - Repair mark - Yes / Bonnet, Headlight - Repair mark - Yes / (R) Front Fender, Molding - Repair mark - Yes / (R) Front Door, Molding - Repair mark - Yes / (R) Rear Door, Molding - Repair mark - Yes / (R) Rear Fender, Molding - Repair mark - Yes / Front Bumper, Grille, Lamps - Crack, Gap - Large / Bonnet, Headlight - Crack, Gap - Large / (L) Front Fender, Molding - Dent - Medium / (L) Front Door, Molding - Scratch - Large / (L) Mirror - Scratch - Minimal / (L) Rear Door, Molding - Scratch - Large / (L) Rear Fender, Molding - Scratch - Medium / Rear Bumper, Lamps, Panels - Scratch - Medium / Trunk Hood, Rear Gate - Scratch & Dent - Small / (R) Rear Fender, Molding - Scratch - Large / (R) Rear Door, Molding - Scratch & Dent - Medium / (R) Step, In-panel, Side Spoiler - Repair mark - Yes / (L) Step, In-panel, Side Spoiler - Repair mark - Yes / (R) Step, In-panel, Side Spoiler - Scratch & Dent - Small / (L) Step, In-panel, Side Spoiler - Scratch - Minimal / (R) Front Door, Molding - Scratch - Minimal / (R) Mirror - Scratch - Minimal / (R) Front Fender, Molding - Scratch - Small / Roof - Scratch & Dent - Small
<b>Frame Evaluation :</b> <span style="float: right;"><b>D</b></span>	<b>Functional Evaluation :</b> <span style="float: right;"><b>E</b></span>
<b>Remarks</b> Right Front Pillar - Condition of Welding ? - Yes / Right Front Inside Panel (Front Side) - Traces of Bending, or Marks of Panel Repair ? - Yes / Left Front Inside Panel (Front Side) - Traces of Bending, or Marks of Panel Repair ? - Yes / Left Front Pillar - Traces of Bending, or Marks of Panel Repair ? - Yes / Left Center Pillar - Traces of Bending, or Marks of Panel Repair ? - Yes / Rear Side Member & Trunk Room Floor - Traces of Bending, or Marks of Panel Repair ? - Yes	<b>Remarks</b> Retractable Mirror - Issue - Yes / Warning Lamps - Issue - Yes / Power Window (each) - Stuck, Gap - Yes / Door Lock - Issue - Yes / Shift Shock - Function - Weak / Air Conditioner - Function - Weak / Audio, Radio - Issue - Yes / Reverse Camera - N/A - Yes / Turn Signal, Hazard Flasher - Issue - Yes / Head Light, High Beam - Issue - Yes / Lamps (Brake, Tail, Fog) - Issue - Yes / Wiper - Function - Weak / Horn - Issue - Yes / Spare Key - Issue - Unexist

**Inspector Notes**

With LTO plate, No warranty booklet and Spare tire and Jack and Tools, No Spare key, Scratch headlight and tail light, crack headlight and tail light, Worn Tires, foul smell, No spare key, no reverse camera, horn issue, head unit issue, Room light issue, headlight issue, plate light issue, driver side window stock up.