

General Information

Date & Time: 27, Oct, 2025 15:16

Make	Ford	Model	Explorer
YOM	2014	Odo Meter Reading	88,732
Registration No.	AAL4722	Chassis No.	1FM5J7F90EGB05341
CC	2.0	Transmission	A/T
Fuel Type	Gas	Type of Body	Wagon
Colour	White		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	167.0	196	158	147
2	Boot Lid	298.3	211	494	190
3	Roof	136.2	127	170	118/130
4	Left Front Fender	148.3	139	159	147
5	Left Front Door	139.6	146	142	131
6	Center Panel Left				
7	Left Rear Door	135.3	132	134	140
8	Left Back Panel	136.6	163	122	125
9	Right Front Fender	158.6	167	159	150
10	Right Front Door	170.0	166	168	176
11	Center Panel Right				
12	Right Rear Door	255.3	292	236	238
13	Right Back Panel	139.0	130	141	146

Overall Evaluation :

C

Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

Interior Evaluation : C	Exterior Evaluation : C
 <p>a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain</p>	 <p>A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap</p>
<p>Remarks Overall Interior - Worn as per age - Yes / Overall Interior - Smell - Yes / (L) Front Seat - Worn - Yes / (R) Front Seat - Worn - Yes / Rear Seat - Worn - Yes / Steering Wheel - Worn, Peel, Crack - Small / Dashboard - Worn, Scratch, Cut, Crack - Small / Console, Switches, Vents - Worn, Scratch, Cut, Crack - Small / Ceiling - Loose, Deformed - Small</p>	<p>Remarks Trunk Hood, Rear Gate - Repair Traces - Yes / (R) Rear Door - Repair Traces - Yes / (L) Mirror - Scratch - Minimal / (L) Rear Door, Molding - Scratch & Dent - Minimal / (L) Front Door, Molding - Scratch - Small / (L) Rear Fender, Molding - Scratch - Small / Trunk Hood, Rear Gate - Scratch - Small / Rear Bumper, Lamps, Panels - Scratch - Small / (R) Rear Fender, Molding - Scratch - Minimal / (R) Front Door, Molding - Dent - Small / (R) Rear Door, Molding - Scratch & Dent - Small / (R) Front Fender, Molding - Scratch - Minimal / (L) Front Fender, Molding - Scratch - Minimal / Front Bumper, Grille, Lamps - Repair mark - Yes / Front Bumper, Grille, Lamps - Scratch - Small / (R) Mirror - Scratch - Minimal / Roof - Scratch & Dent - Small / Bonnet, Headlight - Scratch - Small</p>
Frame Evaluation : A	Functional Evaluation : D
<p>Remarks Defects not found</p>	<p>Remarks Warning Lamps - Issue - Yes / Air Conditioner - Function - Weak / Head Light, High Beam - Issue - Yes / Lamps (Brake, Tail, Fog) - Issue - Yes / Wiper - Function - Weak / Spare Key - Issue - Unexist</p>

<p>Inspector Notes</p>
<p>With LTO plate and Sparetire and Incomplete Tools, No Jack and Warranty booklet, scratch headlight and tail light, signal light issue, headlight issue, plate light issue, Room light issue, air-conditioned issue, foul smell, No spare key.</p>