

General Information

Date & Time: 30, Oct, 2025 13:51

Make	Toyota	Model	Vios
YOM	2025	Odo Meter Reading	24,214
Registration No.	NHS8606	Chassis No.	PA1B18F33R4267097
CC	1.3	Transmission	CVT
Fuel Type	Gas	Type of Body	Sedan
Colour	Blue		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	116.3	118	121	110
2	Boot Lid	108.0	103	111	110
3	Roof	103.9	111	102	100/103
4	Left Front Fender	98.9	102	95	100
5	Left Front Door	109.3	108	110	110
6	Center Panel Left				
7	Left Rear Door	114.6	121	113	110
8	Left Back Panel	559.6	473	1,093	113
9	Right Front Fender	101.2	105	100	99
10	Right Front Door	108.6	112	110	104
11	Center Panel Right				
12	Right Rear Door	113.3	116	111	113
13	Right Back Panel	112.9	100	110	129

Overall Evaluation :

B

Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

Interior Evaluation : C	Exterior Evaluation : C
 <p>a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain</p>	 <p>A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap</p>
<p>Remarks Dashboard - Traces of Adhesive Tape - Yes / (R) Front Seat - Grime - Large / (R) Front Floor Mat - Worked - Small / (R) Front Trim - Grime - Small / (L) Front Trim - Grime - Small</p>	<p>Remarks (L) Rear Fender - Repair Traces - Yes / Front Bumper, Grille, Lamps - Scratch - Medium / Bonnet, Headlight - Dent - Small / Trunk Hood, Rear Gate - Crack, Gap - Medium / Rear Bumper, Lamps, Panels - Scratch - Medium / (R) Rear Door, Molding - Scratch - Medium / (R) Front Door, Molding - Dent - Small / (R) Front Fender, Molding - Scratch - Small / (L) Rear Fender, Molding - Scratch & Dent - Medium / (L) Rear Door, Molding - Scratch - Medium</p>
Frame Evaluation : A	Functional Evaluation : A
<p>Remarks Defects not found</p>	<p>Remarks Reverse Camera - N/A - Yes / Spare Key - Issue - Unexist</p>

<p>Inspector Notes</p>
<p>with warranty booklet and spare tire / with LTO plate/ no tools and jack</p>