

General Information

Date & Time: 28, Nov, 2025 07:20

Make	Toyota	Model	Fortuner
YOM	2023	Odo Meter Reading	16,283
Registration No.	FAP1471	Chassis No.	MHFCB8GSXP0529533
CC	2.4	Transmission	M/T
Fuel Type	Diesel	Type of Body	SUV
Colour	White		

Body / Panel Condition




#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet				
2	Boot Lid				
3	Roof				
4	Left Front Fender				
5	Left Front Door				
6	Center Panel Left				
7	Left Rear Door				
8	Left Back Panel				
9	Right Front Fender				
10	Right Front Door				
11	Center Panel Right				
12	Right Rear Door				
13	Right Back Panel				

Overall Evaluation :

E

Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

Interior Evaluation : B	Exterior Evaluation : N / A
<div style="text-align: center;">  </div> <p>a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain</p>	
Remarks (R) Front Floor Mat - Missing - Yes / Mat Other - Missing - Yes / (L) Front Floor Mat - Missing - Yes / Ceiling - Grime - Small / (R) Rear Trim - Grime - Small / (L) Rear Trim - Grime - Small / (L) Front Trim - Grime - Minimal / (R) Front Trim - Grime - Minimal	Remarks Defects not found
Frame Evaluation : N / A	Functional Evaluation : N / A
Remarks Defects not found	Remarks Defects not found

Inspector Notes

Towed unit. Damaged Front bumper and front right fender. Front right underchassis issue. Without warranty booklet, tools, and jack. With spare tire and seat cover. 1 key. With LTO plate.