


General Information

Date & Time: 06, Jan, 2025 09:43

Make	Toyota	Model	Avanza
YOM	2024	Mileage	13,207
Registration No.	DBN2963	Chassis No.	MHFAB1BY2P3072158
CC	1.5	Transmission	CVT
Fuel Type	Gas	Type of Body	MPV
Colour	Red		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	99.4	96	105	97
2	Boot Lid	97.3	88	108	96
3	Roof	111.0	119	125	98/102
4	Left Front Fender	87.9	89	86	89
5	Left Front Door	111.0	104	110	119
6	Center Panel Left				
7	Left Rear Door	103.0	107	100	102
8	Left Back Panel	98.2	105	97	93
9	Right Front Fender	90.6	93	94	85
10	Right Front Door	108.3	111	110	104
11	Center Panel Right				
12	Right Rear Door	102.2	101	99	107
13	Right Back Panel	99.3	94	98	106

Overall Evaluation :

A

Disclaimer

This Grading Report is intended to record the general appearance and condition of the interior, exterior & frame of the vehicle. This is not a detailed inspection report. This is issued on the date and time given herein and the company shall not be liable for the condition of the vehicle after this date and time. Any disputes regarding this report shall not be grounds for arbitration.

Interior Evaluation : A	Exterior Evaluation : B
 a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain	 A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap
Remarks Defects not found	Remarks (R) Rear Fender, Molding - Scratch - Small / (R) Mirror - Scratch - Small / (R) Front Door, Molding - Scratch - Small / (R) Rear Door, Molding - Scratch - Small / Front Bumper, Grille, Lamps - Scratch - Small
Frame Evaluation : A	Functional Evaluation : A
Remarks Defects not found	Remarks Defects not found

Inspector Notes
with warranty booklet. no tools and user manual.