

General Information

Date & Time: 05, Nov, 2025 08:56

Make	Toyota	Model	Hilux
YOM	2023	Odo Meter Reading	65,729
Registration No.	DBH5770	Chassis No.	MR0JB8DD6P3210932
CC	2.4	Transmission	A/T
Fuel Type	Diesel	Type of Body	Pickup
Colour	Black		

Body / Panel Condition



#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	120.3	116	127	118
2	Boot Lid	111.5	99	116	120
3	Roof	116.5	119	120	114/113
4	Left Front Fender	110.6	112	107	113
5	Left Front Door	104.3	110	100	103
6	Center Panel Left				
7	Left Rear Door	103.5	107	105	99
8	Left Back Panel	105.0	108	105	102
9	Right Front Fender	105.2	115	98	103
10	Right Front Door	104.6	107	104	103
11	Center Panel Right				
12	Right Rear Door	103.6	103	100	108
13	Right Back Panel	100.9	103	96	104

Overall Evaluation :

C

Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

Interior Evaluation : C	Exterior Evaluation : E
<p>a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain</p>	<p>A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap</p>
<p>Remarks (L) Front Floor Mat - Grime - Small / Mat Other - Grime - Small / Ceiling - Grime - Minimal / (R) Front Seat - Grime - Small / (L) Front Seat - Worn - Yes / Console, Switchs, Vents - Worn, Scratch, Cut, Crack - Minimal / Rear Seat - Grime - Medium / (R) Front Trim - Grime - Small / (L) Front Trim - Grime - Small / (R) Rear Trim - Grime - Minimal / (L) Rear Trim - Grime - Minimal / Dashboard - Traces of Adhesive Tape - Yes / Glove Box - Loose, Deformed - Medium</p>	<p>Remarks (R) Front Fender, Molding - Scratch - Small / (R) Mirror - Scratch - Minimal / (R) Front Door, Molding - Scratch - Small / (R) Rear Door, Molding - Scratch - Small / (R) Side Gate - Scratch & Dent - Large / Rear Bumper, Lamps, Panels - Repair mark - Yes / Rear Bumper, Lamps, Panels - Scratch - Minimal / Rear Gate - Scratch - Small / (L) Side Gate - Scratch & Dent - Medium / (L) Rear Door, Molding - Scratch - Small / (L) Front Door, Molding - Scratch & Dent - Small / (L) Front Fender, Molding - Scratch - Medium / (L) Mirror - Scratch - Minimal / Front Bumper, Grille, Lamps - Scratch - Medium / Bonnet, Headlight - Scratch - Medium / Roof - Scratch - Small</p>
Frame Evaluation : A	Functional Evaluation : A
<p>Remarks Defects not found</p>	<p>Remarks Spare Key - Issue - Unexist</p>

<p>Inspector Notes</p>
<p>with warranty booklet, no jack and tools, with spare tire, with LTO plate, scratches on headlight and tail light</p>