

General Information

Date & Time: 04, Nov, 2025 09:28

Make	Toyota	Model	Vios
YOM	2024	Odo Meter Reading	4,962
Registration No.	NJF2049	Chassis No.	PA1B18F37R4260606
CC	1.3	Transmission	CVT
Fuel Type	Gas	Type of Body	Sedan
Colour	Red		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	117.0	118	109	124
2	Boot Lid	113.3	120	110	110
3	Roof	110.2	116	114	110/101
4	Left Front Fender	104.3	107	101	105
5	Left Front Door	103.0	106	100	103
6	Center Panel Left				
7	Left Rear Door	110.6	118	110	104
8	Left Back Panel	116.3	119	115	115
9	Right Front Fender	104.2	107	100	106
10	Right Front Door	135.3	150	107	149
11	Center Panel Right				
12	Right Rear Door	134.6	139	128	137
13	Right Back Panel	141.6	141	139	145

Overall Evaluation :

C

Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

Interior Evaluation : A	Exterior Evaluation : E
 <p>a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain</p>	 <p>A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap</p>
Remarks (L) Front Floor Mat - Worked - Small	Remarks (R) Front Door, Molding - Scratch & Dent - Large / (R) Step, In-panel, Side Spoiler - Scratch & Dent - Medium / Front Bumper, Grille, Lamps - Scratch & Dent - Large / (L) Front Door, Molding - Scratch - Large / (R) Rear Door, Molding - Scratch - Large / (L) Rear Fender, Molding - Scratch - Medium / (L) Rear Door, Molding - Scratch - Large
Frame Evaluation : A	Functional Evaluation : B
Remarks Defects not found	Remarks Battery - Weak - Yes / Spare Key - Issue - Unexist

Inspector Notes
no warranty booklet/ no tools/ with jack and spare tire with LTO plate