

General Information

Date & Time: 04, Nov, 2025 14:47

Make	Toyota	Model	Hilux
YOM	2025	Odo Meter Reading	15,136
Registration No.	DBQ5047	Chassis No.	MR0JB8DD3R3553393
CC	2.4	Transmission	M/T
Fuel Type	Diesel	Type of Body	Pickup
Colour	White		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	108.3	102	114	109
2	Boot Lid	87.0	88	89	85
3	Roof	95.8	97	98	94/95
4	Left Front Fender	99.5	109	100	90
5	Left Front Door	96.0	94	93	101
6	Center Panel Left				
7	Left Rear Door	86.7	92	85	83
8	Left Back Panel	106.0	110	101	107
9	Right Front Fender	96.8	94	98	99
10	Right Front Door	89.2	89	88	92
11	Center Panel Right				
12	Right Rear Door	86.8	82	87	92
13	Right Back Panel	97.3	88	103	101

Overall Evaluation :

C

Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

Interior Evaluation : C	Exterior Evaluation : E
<div style="text-align: center; background-color: #cccccc; padding: 50px;">  <p>No Image</p> </div> <p>a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain</p>	 <p>A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap</p>
<p>Remarks Rear Seat - Grime - Medium / (R) Front Seat - Grime - Medium / (L) Front Seat - Grime - Medium / (L) Front Floor Mat - Cut, Crack - Small / (L) Front Floor Mat - Worked - Large / (L) Front Trim - Grime - Small / (R) Front Trim - Grime - Minimal / Ceiling - Grime - Minimal</p>	<p>Remarks (R) Front Fender, Molding - Scratch - Minimal / (R) Rear Door, Molding - Scratch - Small / (R) Front Door, Molding - Scratch - Minimal / (R) Side Gate - Scratch - Small / Rear Bumper, Lamps, Panels - Scratch - Medium / Rear Gate - Scratch - Minimal / Cargo Bed Floor - Modified - Medium / (R) Side Gate - Modified - Medium / (L) Side Gate - Modified - Medium / (L) Side Gate - Scratch - Large / (L) Rear Door, Molding - Scratch - Small / (L) Front Door, Molding - Scratch - Small / (L) Front Fender, Molding - Scratch - Small / Member (Bolted) - Dent - Yes / Front Bumper, Grille, Lamps - Scratch & Dent - Medium / Bonnet, Headlight - Scratch - Small / Roof - Scratch - Minimal</p>
Frame Evaluation : A	Functional Evaluation : A
<p>Remarks Defects not found</p>	<p>Remarks Defects not found</p>

<p>Inspector Notes</p>
<p>with warranty booklet, with jack and tools, with spare tire, with LTO plate, scratches on headlight and tail light</p>