

General Information

Date & Time: 04, Nov, 2025 16:02

Make	Toyota	Model	Vios
YOM	2024	Odo Meter Reading	38,126
Registration No.	NHS2640	Chassis No.	PA1B18F33R4259310
CC	1.3	Transmission	CVT
Fuel Type	Gas	Type of Body	Sedan
Colour	Black		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	120.0	107	123	130
2	Boot Lid	145.7	99	142	196
3	Roof	98.1	99	96	98/100
4	Left Front Fender	103.6	106	105	100
5	Left Front Door	115.6	112	105	130
6	Center Panel Left				
7	Left Rear Door	125.6	136	131	110
8	Left Back Panel	123.6	119	137	115
9	Right Front Fender	105.5	110	109	98
10	Right Front Door	124.0	100	163	109
11	Center Panel Right				
12	Right Rear Door	108.0	113	104	107
13	Right Back Panel	139.6	113	128	178

Overall Evaluation :

C

Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

Interior Evaluation : D	Exterior Evaluation : D
 <p>a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain</p>	 <p>A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap</p>
<p>Remarks (R) Front Seat - Grime - Medium / (R) Front Trim - Grime - Small / Rear Seat - Grime - Large / Trunk Room - Worn, Scratch, Cut, Crack - Small / (L) Front Trim - Grime - Medium / (L) Front Floor Mat - Cut, Crack - Medium / (L) Front Seat - Grime - Small / Console, Switches, Vents - Worn, Scratch, Cut, Crack - Medium / Steering Wheel - Worn, Peel, Crack - Medium / Ceiling - Grime - Medium</p>	<p>Remarks Trunk Hood, Rear Gate - Repair Traces - Yes / (L) Rear Fender, Molding - Scratch & Dent - Large / (L) Step, In-panel, Side Spoiler - Scratch & Dent - Medium / (L) Front Door, Molding - Scratch - Small / (L) Mirror - Scratch - Minimal / Bonnet, Headlight - Scratch - Small / Front Bumper, Grille, Lamps - Scratch - Medium / (R) Front Fender, Molding - Scratch - Small / (R) Front Door, Molding - Scratch - Small / (R) Rear Door, Molding - Scratch - Small / (R) Rear Fender, Molding - Scratch - Small / Trunk Hood, Rear Gate - Scratch - Medium / Roof - Scratch - Small</p>
Frame Evaluation : A	Functional Evaluation : B
<p>Remarks Defects not found</p>	<p>Remarks Battery - Weak - Yes</p>

<p>Inspector Notes</p>
<p>with LTO PLATE /with SPARE TIRE/with JACK IMCOMPLETE TOOLS, NO WARRANTY booklet/,with REVERSE CAMERA,with SPARE KEY,REAR SEAT ISSUE,</p>