

## General Information

Date & Time: 03, Nov, 2025 19:16

|                  |         |                   |                   |
|------------------|---------|-------------------|-------------------|
| Make             | Nissan  | Model             | NV350             |
| YOM              | 2018    | Odo Meter Reading | 92,941            |
| Registration No. | NEA9274 | Chassis No.       | JNT1C2E26Z0054301 |
| CC               | 2.5     | Transmission      | M/T               |
| Fuel Type        | Diesel  | Type of Body      | Van               |
| Colour           | White   |                   |                   |

## Body / Panel Condition





| #  | Area               | Thickness(um) |        |        |          |
|----|--------------------|---------------|--------|--------|----------|
|    |                    | Average       | Value1 | Value2 | Value3/4 |
| 1  | Bonnet             | 80.5          | 79     | 74     | 89       |
| 2  | Boot Lid           | 89.5          | 96     | 73     | 100      |
| 3  | Roof               | 81.8          | 92     | 108    | 68/60    |
| 4  | Left Front Fender  | 78.0          | 79     | 75     | 81       |
| 5  | Left Front Door    | 71.0          | 84     | 68     | 62       |
| 6  | Center Panel Left  |               |        |        |          |
| 7  | Left Rear Door     |               |        |        |          |
| 8  | Left Back Panel    | 80.1          | 83     | 82     | 75       |
| 9  | Right Front Fender | 78.3          | 86     | 75     | 75       |
| 10 | Right Front Door   | 74.5          | 72     | 67     | 85       |
| 11 | Center Panel Right |               |        |        |          |
| 12 | Right Rear Door    | 85.5          | 68     | 115    | 74       |
| 13 | Right Back Panel   | 82.5          | 81     | 83     | 84       |

## Overall Evaluation :

**D**

### Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

| Interior Evaluation : <b>E</b>                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                        | Exterior Evaluation : <b>E</b>                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                    |
|-------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|
|  <p><b>a</b> : Cut, Fray <b>d</b> : Loose, Deformed <b>k</b> : Animal Hair <b>s</b> : Smell <b>t</b> : Cigarette Burns <b>x</b> : Defective <b>y</b> : Stain</p>                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                    |  <p><b>A</b> : Scratch <b>AU</b> : Scratch &amp; Dent <b>B</b> : Modified <b>C</b> : Corrosion <b>G</b> : Stone chip <b>P</b> : Faded <b>S</b> : Rust <b>SC</b> : Rust &amp; Corrosion <b>U</b> : Dent <b>X</b> : Defective <b>Y</b> : Crack, Gap</p>                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                           |
| <p><b>Remarks</b></p> <p>Overall Interior - Smell - Yes / Overall Interior - Worn as per age - Yes / Overall Interior - Animal Hair - Yes / Ceiling - Grime - Large / (L) Front Floor Mat - Missing - Yes / (R) Front Floor Mat - Missing - Yes / Mat Other - Missing - Yes / (R) Front Seat - Worn - Yes / (L) Front Seat - Worn - Yes / Console, Switches, Vents - Worn, Scratch, Cut, Crack - Small / Dashboard - Traces of Adhesive Tape - Yes / Dashboard - Worn, Scratch, Cut, Crack - Small / Steering Wheel - Worn, Peel, Crack - Small / Glove Box - Worn, Scratch, Cut, Crack - Small / Knobs - Worn, Peel, Crack - Small / Room Mirror - Stuck - Yes / Display, Audio System - Stuck - Yes / (L) Front Trim - Worked - Small / (R) Front Trim - Worked - Small / (L) Rear Trim - Worked - Large / (R) Rear Trim - Worked - Large / Rear Seat - Missing - Yes / Carpet - Worked - Large</p> | <p><b>Remarks</b></p> <p>Trunk Hood, Rear Gate - Repair Traces - Yes / Front Panel - Scratch &amp; Dent - Medium / Trunk Hood, Rear Gate - Repair mark - Yes / Front Bumper, Grille, Lamps - Scratch - Large / (R) Front Door, Molding - Scratch &amp; Dent - Medium / (R) Front Fender, Molding - Scratch - Small / (R) Mirror - Scratch - Minimal / (R) Step, In-panel, Side Spoiler - Scratch &amp; Dent - Large / (R) Rear Door, Molding - Scratch &amp; Dent - Large / (R) Rear Fender, Molding - Scratch &amp; Dent - Large / Rear Bumper, Lamps, Panels - Scratch - Large / Trunk Hood, Rear Gate - Scratch &amp; Dent - Large / (L) Rear Fender, Molding - Scratch &amp; Dent - Large / (L) Front Door, Molding - Scratch &amp; Dent - Small / (L) Front Fender, Molding - Scratch - Small / (L) Mirror - Scratch - Minimal / Roof - Scratch - Medium</p> |
| Frame Evaluation : <b>A</b>                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                           | Functional Evaluation : <b>E</b>                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                  |
| <p><b>Remarks</b></p> <p>Defects not found</p>                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                        | <p><b>Remarks</b></p> <p>Warning Lamps - Issue - Yes / Power Window (each) - Stuck, Gap - Yes / Air Conditioner - Function - Weak / Battery - Weak - Yes / Reverse Camera - N/A - Yes / Parking Brake - Function - Weak / Head Light, High Beam - Issue - Yes / Lamps (Brake, Tail, Fog) - Issue - Yes / Wiper - Function - Weak / Horn - Issue - Yes / Spare Key - Issue - Unexist</p>                                                                                                                                                                                                                                                                                                                                                                                                                                                                           |

| Inspector Notes                                                                                                                                                                                                                                                                                                                                                                                                           |
|---------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|
| <p>With LTO plate and Sparetire and Jack and Incomplete Tools, No warranty booklet, No spare key, no reverse camera, scratch and crack tail light and headlight, worn tires and Sparetire, foul smell, possible flooded, warning lamps on, rear emblem missing, adhesive marks on vehicle, busted Plate light and headlight, Room light issue, air-conditioned issue, headlight issue, horn issue, tail light busted.</p> |