


General Information

Date & Time: 07, Nov, 2025 14:29

Make	Toyota	Model	Raize
YOM	2024	Odo Meter Reading	53,134
Registration No.	NKE1162	Chassis No.	MHKAB1BAXRJ091172
CC	1.2	Transmission	CVT
Fuel Type	Gas	Type of Body	SUV
Colour	Gray		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	97.9	99	100	95
2	Boot Lid	90.8	87	102	84
3	Roof	104.9	116	104	98/102
4	Left Front Fender	94.2	84	105	94
5	Left Front Door	110.3	107	116	108
6	Center Panel Left				
7	Left Rear Door	104.6	110	104	100
8	Left Back Panel	88.8	90	86	91
9	Right Front Fender	98.2	100	104	91
10	Right Front Door	107.6	111	106	106
11	Center Panel Right				
12	Right Rear Door	98.3	100	98	97
13	Right Back Panel	93.2	87	99	94

Overall Evaluation :

C

Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

Interior Evaluation : B	Exterior Evaluation : E
 a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain	 A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap
Remarks (R) Front Floor Mat - Grime - Medium / (R) Front Seat - Grime - Small / Rear Seat - Grime - Medium / (L) Front Seat - Grime - Small / (L) Front Floor Mat - Grime - Small / Ceiling - Grime - Small	Remarks Rear Bumper, Lamps, Panels - Scratch & Dent - Large / (L) Rear Fender, Molding - Scratch & Dent - Medium / Trunk Hood, Rear Gate - Scratch & Dent - Large / (R) Rear Fender, Molding - Scratch - Small / (R) Rear Door, Molding - Scratch - Medium / (R) Front Door, Molding - Scratch - Small / (R) Front Fender, Molding - Scratch & Dent - Small / (R) Mirror - Scratch - Minimal / Front Bumper, Grille, Lamps - Scratch - Medium / (L) Mirror - Scratch - Minimal / Bonnet, Headlight - Scratch - Small / (L) Front Fender, Molding - Scratch - Small / (L) Front Door, Molding - Scratch & Dent - Large / (L) Rear Door, Molding - Scratch & Dent - Large / Roof - Dent - Small
Frame Evaluation : A	Functional Evaluation : B
Remarks Defects not found	Remarks Battery - Weak - Yes / Spare Key - Issue - Unexist

Inspector Notes

with LTO plate/with spare tire/with jack No tools/with reverse camera/No warranty booklet/plate light issue /No spare key