

General Information

Date & Time: 10, Jan, 2025 10:22

Make	Toyota	Model	Vios
YOM	2024	Mileage	38,512
Registration No.	EAJ3403	Chassis No.	PA1B18F39P4230794
CC	1.3	Transmission	CVT
Fuel Type	Gas	Type of Body	Sedan
Colour	Silver		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	105.5	108	99	110
2	Boot Lid	105.4	112	99	105
3	Roof	94.8	93	94	95/97
4	Left Front Fender	92.6	92	94	92
5	Left Front Door	98.2	98	97	99
6	Center Panel Left				
7	Left Rear Door	98.7	105	95	97
8	Left Back Panel	106.8	117	107	97
9	Right Front Fender	103.3	102	103	105
10	Right Front Door	97.9	98	100	96
11	Center Panel Right				
12	Right Rear Door	97.6	96	96	101
13	Right Back Panel	106.9	98	101	122

Overall Evaluation :

A

Disclaimer

This Grading Report is intended to record the general appearance and condition of the interior, exterior & frame of the vehicle. This is not a detailed inspection report. This is issued on the date and time given herein and the company shall not be liable for the condition of the vehicle after this date and time. Any disputes regarding this report shall not be grounds for arbitration.

Interior Evaluation : B	Exterior Evaluation : B
 a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain	 A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap
Remarks Rear Seat - Grime - Medium / (R) Front Seat - Grime - Small	Remarks (R) Mirror - Scratch - Small / Rear Bumper, Lamps, Panels - Dent - Minimal / (L) Rear Fender, Molding - Scratch - Small / Front Bumper, Grille, Lamps - Scratch & Dent - Small / (R) Step, In-panel, Side Spoiler - Scratch - Small / (R) Front Door, Molding - Scratch - Small
Frame Evaluation : A	Functional Evaluation : A
Remarks Defects not found	Remarks Reverse Camera - N/A - Yes

Inspector Notes
no spare tire and warranty booklet. with tools.