

General Information

Date & Time: 10, Jan, 2025 09:50

Make	Toyota	Model	Vios
YOM	2023	Mileage	6,374
Registration No.	EAG3359	Chassis No.	PA1B18F38P4207619
CC	1.3	Transmission	CVT
Fuel Type	Gas	Type of Body	Sedan
Colour	Red		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	106.6	104	105	111
2	Boot Lid	103.3	109	100	101
3	Roof	98.5	105	93	103/93
4	Left Front Fender	93.2	96	90	94
5	Left Front Door	101.8	116	93	96
6	Center Panel Left				
7	Left Rear Door	96.9	97	102	92
8	Left Back Panel	107.0	110	100	111
9	Right Front Fender	95.8	94	96	98
10	Right Front Door	92.1	89	88	100
11	Center Panel Right				
12	Right Rear Door	94.2	93	92	98
13	Right Back Panel	98.5	89	102	105

Overall Evaluation :

A

Disclaimer

This Grading Report is intended to record the general appearance and condition of the interior, exterior & frame of the vehicle. This is not a detailed inspection report. This is issued on the date and time given herein and the company shall not be liable for the condition of the vehicle after this date and time. Any disputes regarding this report shall not be grounds for arbitration.

Interior Evaluation : A	Exterior Evaluation : A
 a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain	 A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap
Remarks Defects not found	Remarks Front Bumper, Grille, Lamps - Scratch - Minimal
Frame Evaluation : A	Functional Evaluation : A
Remarks Defects not found	Remarks Spare Key - Issue - Unexist

Inspector Notes

with spare tire/jack and incomplete tool/No warranty booklet/front left fender black cover missing