

General Information

Date & Time: 26, Nov, 2025 14:53

Make	Toyota	Model	Wigo
YOM	2022	Odo Meter Reading	37,230
Registration No.	NFL4786	Chassis No.	MHKA4DF5FNJ068496
CC	1.0	Transmission	A/T
Fuel Type	Gas	Type of Body	Hatchback
Colour	Silver		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	131.0	134	123	136
2	Boot Lid	145.6	127	158	152
3	Roof	128.5	115	134	125/140
4	Left Front Fender	145.6	134	139	164
5	Left Front Door	151.6	142	142	171
6	Center Panel Left				
7	Left Rear Door	167.0	189	155	157
8	Left Back Panel	147.0	152	153	136
9	Right Front Fender	148.6	177	147	122
10	Right Front Door	140.6	156	133	133
11	Center Panel Right				
12	Right Rear Door	160.3	153	166	162
13	Right Back Panel	169.6	178	166	165

Overall Evaluation :

C

Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

Interior Evaluation : C	Exterior Evaluation : C
 <p>a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain</p>	 <p>A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap</p>
<p>Remarks Rear Seat - Grime - Large / (R) Front Trim - Grime - Minimal / (R) Front Seat - Grime - Small / (L) Front Trim - Grime - Minimal / (L) Front Seat - Grime - Small / Ceiling - Grime - Small / Dashboard - Worn, Scratch, Cut, Crack - Small</p>	<p>Remarks Bonnet - Repair Traces - Yes / Rear Bumper, Lamps, Panels - Scratch - Small / (L) Rear Door, Molding - Scratch - Small / (L) Front Door, Molding - Scratch - Minimal / (L) Front Fender, Molding - Scratch - Minimal / Bonnet, Headlight - Dent - Minimal / Front Bumper, Grille, Lamps - Scratch - Medium / (R) Mirror - Scratch - Small / (R) Rear Fender, Molding - Scratch - Small / (R) Front Door, Molding - Scratch - Minimal / (R) Rear Door, Molding - Scratch - Minimal / Trunk Hood, Rear Gate - Scratch - Small / Roof - Repair mark - Yes</p>
Frame Evaluation : A	Functional Evaluation : B
<p>Remarks Defects not found</p>	<p>Remarks Battery - Weak - Yes / Spare Key - Issue - Unexist</p>

<p>Inspector Notes</p>
<p>with LTO plate/with spare tire/No spare key/with jack and incomplete tools/with reverse camera/with warranty booklet/possible re-painted</p>