

## General Information

Date & Time: 05, Nov, 2025 16:16

<b>Make</b>	Toyota	<b>Model</b>	Vios
<b>YOM</b>	2021	<b>Odo Meter Reading</b>	28,169
<b>Registration No.</b>	NGT3176	<b>Chassis No.</b>	PA1B18F38M4135879
<b>CC</b>	1.3	<b>Transmission</b>	CVT
<b>Fuel Type</b>	Gas	<b>Type of Body</b>	Sedan
<b>Colour</b>	Red		

## Body / Panel Condition



#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	103.2	109	98	103
2	Boot Lid	113.6	111	110	120
3	Roof	96.7	97	97	85/108
4	Left Front Fender	93.1	91	93	95
5	Left Front Door	96.1	99	92	98
6	Center Panel Left				
7	Left Rear Door	103.6	116	100	95
8	Left Back Panel	115.3	119	116	111
9	Right Front Fender	125.6	128	121	128
10	Right Front Door	125.3	134	118	124
11	Center Panel Right				
12	Right Rear Door	97.9	92	96	106
13	Right Back Panel	101.8	100	103	103

Overall Evaluation :

**D**

### Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

