

## General Information

Date & Time: 19, Nov, 2025 19:25

<b>Make</b>	Toyota	<b>Model</b>	Vios
<b>YOM</b>	2022	<b>Odo Meter Reading</b>	72,254
<b>Registration No.</b>	FAJ7548	<b>Chassis No.</b>	PA1B18F39N4184090
<b>CC</b>	1.3	<b>Transmission</b>	CVT
<b>Fuel Type</b>	Gas	<b>Type of Body</b>	Sedan
<b>Colour</b>	Silver		

## Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	129.0	132	127	128
2	Boot Lid	121.0	121	119	123
3	Roof	101.4	104	97	100/105
4	Left Front Fender	233.0	246	322	131
5	Left Front Door	118.0	110	115	129
6	Center Panel Left				
7	Left Rear Door	121.6	136	121	108
8	Left Back Panel	115.0	119	109	117
9	Right Front Fender	105.4	105	115	96
10	Right Front Door	111.0	114	112	107
11	Center Panel Right				
12	Right Rear Door	115.6	109	112	126
13	Right Back Panel	278.3	307	281	247

## Overall Evaluation :

**D**

### Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

<b>Interior Evaluation :</b> <span style="float: right; color: red; font-weight: bold;">D</span>	<b>Exterior Evaluation :</b> <span style="float: right; color: red; font-weight: bold;">E</span>
 <p><b>a</b> : Cut, Fray <b>d</b> : Loose, Deformed <b>k</b> : Animal Hair <b>s</b> : Smell <b>t</b> : Cigarette Burns <b>x</b> : Defective <b>y</b> : Stain</p>	 <p><b>A</b> : Scratch <b>AU</b> : Scratch &amp; Dent <b>B</b> : Modified <b>C</b> : Corrosion <b>G</b> : Stone chip <b>P</b> : Faded <b>S</b> : Rust <b>SC</b> : Rust &amp; Corrosion <b>U</b> : Dent <b>X</b> : Defective <b>Y</b> : Crack, Gap</p>
<p><b>Remarks</b> Rear Seat - Grime - Medium / (L) Front Seat - Worn - Yes / Ceiling - Grime - Medium / (R) Front Trim - Grime - Small / (L) Front Trim - Grime - Small / Mat Other - Missing - Yes / (R) Front Floor Mat - Missing - Yes / (L) Front Floor Mat - Missing - Yes / Trunk Room - Loose, Deformed - Medium / Glove Box - Loose, Deformed - Medium / (R) Rear Trim - Cut, Crack - Small / Carpet - Worked - Large</p>	<p><b>Remarks</b> Bonnet - Repair Traces - Yes / (L) Front Fender - Repair Traces - Yes / Trunk Hood, Rear Gate - Repair Traces - Yes / (R) Rear Fender - Repair Traces - Yes / (R) Front Fender, Molding - Scratch - Small / (R) Rear Door, Molding - Scratch &amp; Dent - Large / (R) Step, In-panel, Side Spoiler - Repair mark - Yes / (R) Step, In-panel, Side Spoiler - Scratch &amp; Dent - Small / (R) Front Door, Molding - Scratch - Medium / (R) Rear Fender, Molding - Dent - Medium / Rear Bumper, Lamps, Panels - Repair mark - Yes / Rear Bumper, Lamps, Panels - Scratch - Medium / Trunk Hood, Rear Gate - Scratch &amp; Dent - Medium / (L) Rear Fender, Molding - Dent - Medium / (L) Rear Door, Molding - Scratch &amp; Dent - Large / (L) Front Door, Molding - Dent - Large / (L) Mirror - Crack - Damaged / (L) Front Fender, Molding - Repair mark - Yes / Bonnet, Headlight - Dent - Medium / Front Bumper, Grille, Lamps - Repair mark - Yes / (L) Mirror - Scratch - Small / (L) Front Fender, Molding - Scratch &amp; Dent - Small / Front Bumper, Grille, Lamps - Scratch - Medium / Roof - Scratch - Small</p>
<b>Frame Evaluation :</b> <span style="float: right; color: red; font-weight: bold;">A</span>	<b>Functional Evaluation :</b> <span style="float: right; color: red; font-weight: bold;">C</span>
<p><b>Remarks</b> Defects not found</p>	<p><b>Remarks</b> Retractable Mirror - Issue - Yes / Air Conditioner - Function - Weak / Audio, Radio - Issue - Yes / Reverse Camera - N/A - Yes / Turn Signal, Hazard Flasher - Issue - Yes / Lamps (Brake, Tail, Fog) - Issue - Yes / Spare Key - Issue - Unexist</p>

<p><b>Inspector Notes</b></p>
<p>no warranty booklet, no jack and tools, no spare tire, with LTO plate, possible flooding, scratches on headlight and tail light, yellowish headlight, air-con issue, headlight unit replaced, front bumper partially missing, reverse and signal light issue, trunk cover missing, left side mirror loose, retractable mirror control missing, abnormal noise on blower, crack cooling, engine hood issue, front emblem missing, front mudguard missing, missing studbolt on front right wheel</p>