

General Information

Date & Time: 10, Dec, 2025 20:00

Make	Toyota	Model	Vios
YOM	2025	Odo Meter Reading	23,973
Registration No.	FAQ9203	Chassis No.	PA1B18F36R4266879
CC	1.3	Transmission	CVT
Fuel Type	Gas	Type of Body	Sedan
Colour	Red		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	128.0	123	126	135
2	Boot Lid	115.3	113	112	121
3	Roof	113.7	125	106	111/113
4	Left Front Fender	102.0	104	102	100
5	Left Front Door	155.6	149	158	160
6	Center Panel Left				
7	Left Rear Door	123.6	127	119	125
8	Left Back Panel	123.0	131	123	115
9	Right Front Fender	206.6	210	199	211
10	Right Front Door	124.3	128	130	115
11	Center Panel Right				
12	Right Rear Door	114.6	118	108	118
13	Right Back Panel	118.0	120	113	121

Overall Evaluation :

B

Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

Interior Evaluation : B	Exterior Evaluation : B
 <p>a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain</p>	 <p>A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap</p>
<p>Remarks Ceiling - Grime - Small / (R) Front Floor Mat - Grime - Medium / (R) Front Trim - Grime - Small / Mat Other - Grime - Medium / (L) Front Floor Mat - Worked - Small / (L) Front Trim - Grime - Small</p>	<p>Remarks (R) Front Fender - Repair Traces - Yes / (L) Rear Door, Molding - Scratch - Minimal / Trunk Hood, Rear Gate - Scratch - Small / Rear Bumper, Lamps, Panels - Scratch & Dent - Small / (R) Rear Fender, Molding - Scratch - Minimal / (R) Front Door, Molding - Scratch - Small / (R) Front Fender, Molding - Scratch - Small / Front Bumper, Grille, Lamps - Scratch - Small / (R) Front Fender, Molding - Repair mark - Yes</p>
Frame Evaluation : A	Functional Evaluation : B
<p>Remarks Defects not found</p>	<p>Remarks Battery - Weak - Yes / Spare Key - Issue - Unexist</p>

<p>Inspector Notes</p>
<p>Without warranty booklet, spare tire and tools. With jack and seat cover. 1 key. With LTO plate.</p>