

General Information

Date & Time: 13, Jan, 2025 13:21

Make	Toyota	Model	Vios
YOM	2023	Mileage	19,903
Registration No.	CBI1269	Chassis No.	PA1B18F31P4207185
CC	1.3	Transmission	CVT
Fuel Type	Gas	Type of Body	Sedan
Colour	Red Mica Metallic		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	99.7	100	103	96
2	Boot Lid	101.7	99	102	104
3	Roof	96.4	100	101	90/94
4	Left Front Fender	129.9	144	153	93
5	Left Front Door	98.8	100	100	97
6	Center Panel Left				
7	Left Rear Door	100.8	107	105	91
8	Left Back Panel	102.9	107	104	98
9	Right Front Fender	88.0	89	87	89
10	Right Front Door	88.8	89	87	91
11	Center Panel Right				
12	Right Rear Door	95.1	88	92	106
13	Right Back Panel	146.3	159	128	152

Overall Evaluation :

B

Disclaimer

This Grading Report is intended to record the general appearance and condition of the interior, exterior & frame of the vehicle. This is not a detailed inspection report. This is issued on the date and time given herein and the company shall not be liable for the condition of the vehicle after this date and time. Any disputes regarding this report shall not be grounds for arbitration.

Interior Evaluation : B	Exterior Evaluation : B
 a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain	 A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap
Remarks Rear Seat - Grime - Medium / (L) Front Floor Mat - Worked - Small	Remarks (R) Step - Repair Traces - Yes / (L) Front Fender - Repair Traces - Yes / (L) Rear Fender, Molding - Dent - Minimal / Front Bumper, Grille, Lamps - Dent - Small / (R) Front Fender, Molding - Scratch - Small / (R) Front Door, Molding - Scratch - Small / (R) Rear Door, Molding - Scratch - Small / (R) Rear Fender, Molding - Repair mark - Yes / (L) Front Door, Molding - Dent - Small / (L) Step, In-panel, Side Spoiler - Scratch - Small
Frame Evaluation : A	Functional Evaluation : E
Remarks Defects not found	Remarks Retractable Mirror - Issue - Yes / Warning Lamps - Issue - Yes / Panel, Meter - Issue - Yes / Power Window (each) - Stuck, Gap - Yes / Door Lock - Issue - Yes / Power Seat - Issue - Yes / Power Steering - Issue - Yes / Battery - Weak - Yes / Remote Key & Smart entry - Issue - Yes / Audio, Radio - Issue - Yes / Reverse Camera - N/A - Yes / Turn Signal, Hazard Flasher - Issue - Yes / Head Light, High Beam - Issue - Yes / Lamps (Brake, Tail, Fog) - Issue - Yes / Wiper - Function - Weak / Horn - Issue - Yes / Spare Key - Issue - Unexist

Inspector Notes

no LTO plate/ no warranty booklet/ no tools / vehicle not moving/ with spare tire and jack