

General Information

Date & Time: 10, Dec, 2025 19:59

Make	Toyota	Model	Vios
YOM	2025	Odo Meter Reading	35,327
Registration No.	FAS8055	Chassis No.	PA1B18F38S4282507
CC	1.3	Transmission	CVT
Fuel Type	Gas	Type of Body	Sedan
Colour	Silver		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	119.3	127	110	121
2	Boot Lid	118.6	114	119	123
3	Roof	103.5	102	102	102/108
4	Left Front Fender	102.3	103	100	104
5	Left Front Door	107.0	107	114	100
6	Center Panel Left				
7	Left Rear Door	111.3	111	110	113
8	Left Back Panel	112.3	120	109	108
9	Right Front Fender	101.6	100	100	105
10	Right Front Door	102.3	105	102	100
11	Center Panel Right				
12	Right Rear Door	106.0	101	103	114
13	Right Back Panel	117.0	114	112	125

Overall Evaluation :

B

Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

Interior Evaluation : D	Exterior Evaluation : B
 <p>a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain</p>	 <p>A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap</p>
<p>Remarks Ceiling - Grime - Small / (R) Front Seat - Grime - Medium / (R) Front Floor Mat - Grime - Medium / (R) Front Trim - Grime - Medium / Rear Seat - Grime - Large / Mat Other - Grime - Large / (L) Front Trim - Grime - Medium / (L) Front Seat - Grime - Medium / (L) Front Floor Mat - Worked - Small</p>	<p>Remarks (R) Front Fender, Molding - Scratch - Small / (R) Mirror - Scratch - Minimal / (R) Rear Door, Molding - Scratch - Minimal / (R) Front Door, Molding - Scratch - Small / (R) Rear Fender, Molding - Scratch - Minimal / Rear Bumper, Lamps, Panels - Scratch - Small / (L) Front Door, Molding - Scratch - Small / (L) Front Fender, Molding - Scratch - Small / Front Bumper, Grille, Lamps - Scratch & Dent - Medium</p>
Frame Evaluation : A	Functional Evaluation : A
<p>Remarks Defects not found</p>	<p>Remarks Spare Key - Issue - Unexist</p>

<p>Inspector Notes</p>
<p>Possible flooding. Moist at instrument panel. With warranty booklet. Without spare tire, jack, tools and seat cover. 1 key. With LTO plate.</p>