

General Information

Date & Time: 10, Nov, 2025 17:04

Make	Suzuki	Model	Carry
YOM	2025	Odo Meter Reading	11,792
Registration No.	NKO5387	Chassis No.	MHYDC61T2SJ270697
CC	1.5	Transmission	M/T
Fuel Type	Gas	Type of Body	Utility Vehicle
Colour	White		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	113.6	123	111	107
2	Boot Lid	131.6	142	102	151
3	Roof	99.0	107	112	89/88
4	Left Front Fender	110.3	107	110	114
5	Left Front Door	107.4	99	119	104
6	Center Panel Left				
7	Left Rear Door				
8	Left Back Panel	105.8	108	95	114
9	Right Front Fender	125.3	115	127	134
10	Right Front Door	108.6	111	117	98
11	Center Panel Right				
12	Right Rear Door				
13	Right Back Panel	141.6	142	127	156

Overall Evaluation :

A

Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

Interior Evaluation : A	Exterior Evaluation : A
 a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain	 A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap
Remarks Ceiling - Grime - Small / Glove Box - Worn, Scratch, Cut, Crack - Small	Remarks (R) Side Gate - Scratch & Dent - Small / Rear Bumper, Lamps, Panels - Scratch - Minimal / (L) Side Gate - Scratch - Small / (L) Front Door, Molding - Scratch - Minimal
Frame Evaluation : A	Functional Evaluation : A
Remarks Defects not found	Remarks Reverse Camera - N/A - Yes

Inspector Notes
With Lto plate, with warranty booklet, with spare tire, 2 keys, no jack and tools,