


General Information

Date & Time: 12, Nov, 2025 15:51

Make	Toyota	Model	Vios
YOM	2025	Odo Meter Reading	11,799
Registration No.	CCR4045	Chassis No.	PA1B18F34S4289535
CC	1.3	Transmission	CVT
Fuel Type	Gas	Type of Body	Sedan
Colour	Red		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	115.6	116	118	113
2	Boot Lid	106.3	104	104	111
3	Roof	107.7	111	102	115/103
4	Left Front Fender	99.2	99	100	98
5	Left Front Door	105.6	103	102	112
6	Center Panel Left				
7	Left Rear Door	108.0	113	108	103
8	Left Back Panel	104.3	111	105	97
9	Right Front Fender	108.3	116	108	101
10	Right Front Door	108.0	107	109	108
11	Center Panel Right				
12	Right Rear Door	108.3	109	105	111
13	Right Back Panel	111.6	111	107	117

Overall Evaluation :

A

Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

Interior Evaluation : A	Exterior Evaluation : A
 a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain	 A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap
Remarks Rear Seat - Grime - Minimal	Remarks (R) Mirror - Scratch - Minimal / (R) Front Door, Molding - Scratch - Minimal / (R) Rear Door, Molding - Scratch - Small / (R) Rear Fender, Molding - Scratch - Minimal / Rear Bumper, Lamps, Panels - Scratch - Minimal / (L) Rear Fender, Molding - Scratch - Minimal / (L) Front Door, Molding - Scratch - Small / Front Bumper, Grille, Lamps - Scratch - Minimal
Frame Evaluation : A	Functional Evaluation : A
Remarks Defects not found	Remarks Defects not found

Inspector Notes
With Lto plate, with jack and tools, 2 keys, No spare tire, scratches headlight