


General Information

Date & Time: 13, Jan, 2025 13:14

Make	Toyota	Model	Vios
YOM	2023	Mileage	12,716
Registration No.	NIN9333	Chassis No.	PA1B18F33P4211416
CC	1.3	Transmission	CVT
Fuel Type	Gas	Type of Body	Sedan
Colour	Black		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	112.6	119	106	113
2	Boot Lid	102.6	100	101	107
3	Roof	98.3	106	95	100/92
4	Left Front Fender	91.9	95	90	90
5	Left Front Door	97.9	100	95	99
6	Center Panel Left				
7	Left Rear Door	102.0	108	101	97
8	Left Back Panel	105.0	105	108	102
9	Right Front Fender	95.2	90	88	108
10	Right Front Door	94.1	93	90	99
11	Center Panel Right				
12	Right Rear Door	104.4	95	99	120
13	Right Back Panel	96.8	96	97	98

Overall Evaluation :

B

Disclaimer

This Grading Report is intended to record the general appearance and condition of the interior, exterior & frame of the vehicle. This is not a detailed inspection report. This is issued on the date and time given herein and the company shall not be liable for the condition of the vehicle after this date and time. Any disputes regarding this report shall not be grounds for arbitration.

Interior Evaluation : A	Exterior Evaluation : B
 a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain	 A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap
Remarks Defects not found	Remarks Front Bumper, Grille, Lamps - Scratch & Dent - Medium / (L) Front Door, Molding - Dent - Small / (L) Rear Fender, Molding - Scratch & Dent - Medium / Rear Bumper, Lamps, Panels - Scratch - Medium / (L) Front Fender, Molding - Dent - Minimal
Frame Evaluation : A	Functional Evaluation : E
Remarks Defects not found	Remarks Retractable Mirror - Issue - Yes / Warning Lamps - Issue - Yes / Power Window (each) - Stuck, Gap - Yes / Door Lock - Issue - Yes / Sun Roof - Stuck, Gap - Yes / Power Seat - Issue - Yes / Power Steering - Issue - Yes / Air Conditioner - Function - Weak / Battery - Weak - Yes / Remote Key & Smart entry - Issue - Yes / Audio, Radio - Issue - Yes / Reverse Camera - N/A - Yes / Turn Signal, Hazard Flasher - Issue - Yes / Head Light, High Beam - Issue - Yes / Lamps (Brake, Tail, Fog) - Issue - Yes / Wiper - Function - Weak / Horn - Issue - Yes / Spare Key - Issue - Unexist

Inspector Notes

interior, and frame inspection was not accomplished due to the vehicle does not have a physical key/ not moving vehicle. Hood, trunk and doors cannot be opened.