

General Information

Date & Time: 10, Jan, 2025 14:51

Make	Toyota	Model	Vios
YOM	2023	Mileage	46,802
Registration No.	NIQ1727	Chassis No.	PA1B18F30P4224804
CC	1.3	Transmission	CVT
Fuel Type	Gas	Type of Body	Sedan
Colour	Blue		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	102.6	100	102	106
2	Boot Lid	116.0	109	122	117
3	Roof	127.2	124	131	127/127
4	Left Front Fender	109.0	111	108	108
5	Left Front Door	109.0	110	104	113
6	Center Panel Left				
7	Left Rear Door	118.3	128	112	115
8	Left Back Panel	113.0	124	106	109
9	Right Front Fender	117.3	120	104	128
10	Right Front Door	108.6	109	106	111
11	Center Panel Right				
12	Right Rear Door	115.3	108	118	120
13	Right Back Panel	106.3	102	110	107

Overall Evaluation :

A

Disclaimer

This Grading Report is intended to record the general appearance and condition of the interior, exterior & frame of the vehicle. This is not a detailed inspection report. This is issued on the date and time given herein and the company shall not be liable for the condition of the vehicle after this date and time. Any disputes regarding this report shall not be grounds for arbitration.

Interior Evaluation : A	Exterior Evaluation : C
 a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain	 A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap
Remarks (R) Front Floor Mat - Grime - Small	Remarks (R) Step, In-panel, Side Spoiler - Scratch & Dent - Large / (R) Front Door, Molding - Scratch - Medium / (R) Rear Fender, Molding - Scratch - Medium / Front Bumper, Grille, Lamps - Scratch - Large / Rear Bumper, Lamps, Panels - Scratch - Medium / (L) Rear Fender, Molding - Scratch - Small / (L) Rear Door, Molding - Scratch - Small
Frame Evaluation : A	Functional Evaluation : A
Remarks Defects not found	Remarks Defects not found

Inspector Notes

No reverse camera/with spare tire / incomplete tool/ no jack