

General Information

Date & Time: 26, Nov, 2025 13:15

Make	Toyota	Model	Vios
YOM	2024	Odo Meter Reading	19,860
Registration No.	NHR4037	Chassis No.	PA1B18F33P4229527
CC	1.3	Transmission	CVT
Fuel Type	Gas	Type of Body	Sedan
Colour	Blue		

Body / Panel Condition



#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	107.0	102	106	113
2	Boot Lid	104.0	107	97	108
3	Roof	100.7	99	112	96/96
4	Left Front Fender	96.2	95	96	98
5	Left Front Door	104.0	106	102	104
6	Center Panel Left				
7	Left Rear Door	117.3	121	107	124
8	Left Back Panel	115.3	116	117	113
9	Right Front Fender	103.6	103	105	103
10	Right Front Door	102.1	99	102	105
11	Center Panel Right				
12	Right Rear Door	100.0	100	103	97
13	Right Back Panel	109.6	103	111	115

Overall Evaluation :

B

Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

Interior Evaluation :	B	Exterior Evaluation :	C
<p>a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain</p>		<p>A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap</p>	
<p>Remarks Rear Seat - Grime - Medium / (L) Front Floor Mat - Cut, Crack - Small / (R) Front Seat - Grime - Medium / (L) Front Seat - Grime - Medium / (L) Front Floor Mat - Worked - Small / Overall Interior - Smell - Yes</p>		<p>Remarks (R) Front Fender, Molding - Scratch & Dent - Small / (R) Mirror - Scratch - Minimal / (R) Front Door, Molding - Scratch - Small / (R) Rear Door, Molding - Scratch - Small / (R) Rear Fender, Molding - Scratch & Dent - Small / Rear Bumper, Lamps, Panels - Scratch & Dent - Small / Trunk Hood, Rear Gate - Dent - Minimal / (L) Rear Fender, Molding - Dent - Minimal / (L) Rear Door, Molding - Scratch - Minimal / (L) Front Door, Molding - Scratch - Minimal / (L) Mirror - Scratch - Minimal / (L) Front Fender, Molding - Scratch - Medium / Bonnet, Headlight - Scratch & Dent - Large / Front Bumper, Grille, Lamps - Scratch - Small / Roof - Scratch - Minimal</p>	
Frame Evaluation :	A	Functional Evaluation :	A
<p>Remarks Defects not found</p>		<p>Remarks Reverse Camera - N/A - Yes / Spare Key - Issue - Unexist</p>	

Inspector Notes
with warranty booklet, jack, tools, spare tire, with LTO plate, scratches on tail light