

General Information

Date & Time: 13, Nov, 2025 15:47

Make	Toyota	Model	Vios
YOM	2025	Odo Meter Reading	9,212
Registration No.	CCG4559	Chassis No.	PA1B18F35R4269241
CC	1.3	Transmission	CVT
Fuel Type	Gas	Type of Body	Sedan
Colour	Black		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	105.6	107	102	108
2	Boot Lid	109.6	114	104	111
3	Roof	89.5	96	86	86/90
4	Left Front Fender	91.6	92	93	90
5	Left Front Door	99.6	94	106	99
6	Center Panel Left				
7	Left Rear Door	101.2	104	101	99
8	Left Back Panel	105.0	105	107	103
9	Right Front Fender	99.3	99	99	100
10	Right Front Door	99.5	100	99	100
11	Center Panel Right				
12	Right Rear Door	97.3	99	93	100
13	Right Back Panel	101.3	100	99	105

Overall Evaluation :

A

Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

Interior Evaluation : B	Exterior Evaluation : B
 a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain	 A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap
Remarks Mat Other - Missing - Yes / (L) Front Floor Mat - Worked - Small	Remarks Member (Bolted) - Dent - Yes / (L) Front Fender, Molding - Scratch - Small / (L) Front Door, Molding - Scratch - Minimal / (L) Rear Door, Molding - Scratch & Dent - Minimal / (L) Rear Fender, Molding - Scratch - Small / Roof - Scratch & Dent - Small / Trunk Hood, Rear Gate - Scratch - Small / (R) Rear Door, Molding - Scratch & Dent - Small / (R) Front Door, Molding - Scratch - Small / (R) Front Fender, Molding - Scratch - Minimal / Bonnet, Headlight - Scratch & Dent - Small / Front Bumper, Grille, Lamps - Scratch - Small
Frame Evaluation : A	Functional Evaluation : A
Remarks Defects not found	Remarks Spare Key - Issue - Unexist

Inspector Notes

With LTO plate, No warranty booklet and Sparetire and Jack, No Tools, Scratch headlight and tail light, no spare key, worn tires, adhesive marks on vehicle, busted Plate light, busted Room light, Abnormal vibration on engine.