


General Information

Date & Time: 15, Nov, 2025 10:09

Make	Toyota	Model	Vios
YOM	2024	Odo Meter Reading	16,482
Registration No.	CCC1207	Chassis No.	PA1B18F36P4230705
CC	1.3	Transmission	CVT
Fuel Type	Gas	Type of Body	Sedan
Colour	Silver		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	110.0	112	107	111
2	Boot Lid	119.3	119	114	125
3	Roof	103.5	106	105	101/102
4	Left Front Fender	102.3	96	105	106
5	Left Front Door	102.6	104	100	104
6	Center Panel Left				
7	Left Rear Door	106.3	109	105	105
8	Left Back Panel	107.6	114	102	107
9	Right Front Fender	104.0	102	103	107
10	Right Front Door	93.9	93	90	98
11	Center Panel Right				
12	Right Rear Door	101.8	100	94	111
13	Right Back Panel	107.6	109	100	114

Overall Evaluation :

A

Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

Interior Evaluation : A	Exterior Evaluation : B
 a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain	 A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap
Remarks Mat Other - Grime - Small / (L) Front Floor Mat - Grime - Small	Remarks (R) Front Fender, Molding - Scratch - Minimal / (R) Front Door, Molding - Scratch - Minimal / (R) Rear Door, Molding - Scratch & Dent - Small / (R) Rear Fender, Molding - Scratch - Minimal / Rear Bumper, Lamps, Panels - Scratch & Dent - Small / (L) Rear Fender, Molding - Scratch - Minimal / Roof - Scratch - Small / (L) Front Door, Molding - Scratch - Small / (L) Front Fender, Molding - Scratch & Dent - Medium / Bonnet, Headlight - Scratch - Minimal / Front Bumper, Grille, Lamps - Scratch - Minimal
Frame Evaluation : A	Functional Evaluation : A
Remarks Defects not found	Remarks Reverse Camera - N/A - Yes

Inspector Notes
With Lto plate, with warranty booklet, 3keys,no spare tire, no jack and tools