

General Information

Date & Time: 19, Nov, 2025 15:57

Make	Toyota	Model	Vios
YOM	2025	Odo Meter Reading	8,290
Registration No.	CCG8843	Chassis No.	PA1B18F32S4286519
CC	1.3	Transmission	CVT
Fuel Type	Gas	Type of Body	Sedan
Colour	Blue		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	110.0	111	106	113
2	Boot Lid	120.0	118	116	126
3	Roof	109.6	99	101	101/138
4	Left Front Fender	94.7	96	95	93
5	Left Front Door	106.6	103	105	112
6	Center Panel Left				
7	Left Rear Door	107.2	113	109	100
8	Left Back Panel	115.3	115	119	112
9	Right Front Fender	97.3	95	103	94
10	Right Front Door	100.0	103	97	100
11	Center Panel Right				
12	Right Rear Door	105.6	99	102	116
13	Right Back Panel	105.3	103	103	110

Overall Evaluation :

A

Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

Interior Evaluation : A	Exterior Evaluation : B
 <p>a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain</p>	 <p>A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap</p>
Remarks Defects not found	Remarks Member (Bolted) - Dent - Yes / Bonnet, Headlight - Scratch - Minimal / (L) Rear Door, Molding - Scratch - Minimal / (L) Step, In-panel, Side Spoiler - Scratch & Dent - Minimal / (L) Front Fender, Molding - Scratch - Minimal / Trunk Hood, Rear Gate - Scratch & Dent - Minimal / Rear Bumper, Lamps, Panels - Scratch - Minimal / (L) Rear Fender, Molding - Scratch - Minimal / Roof - Scratch & Dent - Small / (R) Front Fender, Molding - Scratch - Minimal / (R) Front Door, Molding - Scratch & Dent - Minimal / (R) Rear Door, Molding - Scratch - Small / (R) Step, In-panel, Side Spoiler - Scratch & Dent - Minimal / (R) Rear Fender, Molding - Scratch - Minimal
Frame Evaluation : A	Functional Evaluation : B
Remarks Defects not found	Remarks Battery - Weak - Yes / Spare Key - Issue - Unexist

Inspector Notes
With LTO plate, No warranty booklet and Sparetire and Jack and Tools, No Spare key, Scratch headlight and tail light, foul smell, worn tires.