

General Information

Date & Time: 17, Nov, 2025 15:46

Make	Toyota	Model	Raize
YOM	2024	Odo Meter Reading	34,206
Registration No.	CCC6573	Chassis No.	MHKAA1BA6RJ117866
CC	1.0	Transmission	CVT
Fuel Type	Gas	Type of Body	SUV
Colour	Pearl White		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	103.0	103	105	101
2	Boot Lid	94.5	86	107	91
3	Roof	87.6	87	83	85/96
4	Left Front Fender	80.8	81	87	75
5	Left Front Door	90.8	91	89	93
6	Center Panel Left				
7	Left Rear Door	89.1	87	90	91
8	Left Back Panel	79.6	81	76	82
9	Right Front Fender	93.6	90	98	93
10	Right Front Door	95.8	91	97	99
11	Center Panel Right				
12	Right Rear Door	91.9	97	85	94
13	Right Back Panel	86.1	91	83	85

Overall Evaluation :

B

Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

Interior Evaluation : C	Exterior Evaluation : C
 a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain	 A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap
Remarks (L) Front Floor Mat - Worked - Large / (L) Front Seat - Worn - Yes / (R) Front Seat - Grime - Medium / Rear Seat - Grime - Small	Remarks (L) Rear Fender, Molding - Scratch - Minimal / (L) Rear Door, Molding - Scratch & Dent - Small / (L) Front Door, Molding - Scratch & Dent - Minimal / (L) Step, In-panel, Side Spoiler - Scratch - Minimal / (L) Front Fender, Molding - Dent - Minimal / (L) Mirror - Scratch - Minimal / Member (Bolted) - Dent - Yes / Bonnet, Headlight - Scratch & Dent - Minimal / Front Bumper, Grille, Lamps - Scratch - Small / (R) Front Fender, Molding - Scratch - Small / (R) Front Door, Molding - Scratch - Small / (R) Rear Door, Molding - Scratch & Dent - Small / (R) Rear Fender, Molding - Scratch - Minimal / (R) Step, In-panel, Side Spoiler - Scratch - Small / Trunk Hood, Rear Gate - Scratch & Dent - Small / Rear Bumper, Lamps, Panels - Scratch - Small / Roof - Scratch & Dent - Small
Frame Evaluation : A	Functional Evaluation : A
Remarks Defects not found	Remarks Spare Key - Issue - Unexist

Inspector Notes

With LTO plate and Sparetire, No Tools and Jack and Warranty booklet, scratch headlight and tail light, no spare key, Abnormal vibration on engine, foul smell, worn tires, adhesive marks on vehicle.