

General Information

Date & Time: 19, Nov, 2025 14:50

Make	Toyota	Model	Veloz
YOM	2025	Odo Meter Reading	10,676
Registration No.	NKL7604	Chassis No.	MHFAB1BY0R3128049
CC	1.5	Transmission	CVT
Fuel Type	Gas	Type of Body	Wagon
Colour	Black		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	99.0	97	92	108
2	Boot Lid	97.3	106	99	87
3	Roof	113.7	126	126	100/103
4	Left Front Fender	107.0	115	103	103
5	Left Front Door	118.6	112	115	129
6	Center Panel Left				
7	Left Rear Door	116.6	117	106	127
8	Left Back Panel	122.0	111	131	124
9	Right Front Fender	102.7	98	104	106
10	Right Front Door	110.6	122	108	102
11	Center Panel Right				
12	Right Rear Door	112.0	116	103	117
13	Right Back Panel	131.3	136	119	139

Overall Evaluation :

A

Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

Interior Evaluation :	A	Exterior Evaluation :	B
			
<p>a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain</p>		<p>A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap</p>	
<p>Remarks Trunk Room - Worn, Scratch, Cut, Crack - Small</p>		<p>Remarks (R) Front Door, Molding - Scratch - Minimal / (R) Rear Door, Molding - Scratch - Minimal / Rear Bumper, Lamps, Panels - Scratch & Dent - Medium / Trunk Hood, Rear Gate - Scratch - Small / (L) Front Door, Molding - Scratch - Small / (L) Front Fender, Molding - Scratch - Small / Front Bumper, Grille, Lamps - Scratch & Dent - Small</p>	
Frame Evaluation :	A	Functional Evaluation :	A
<p>Remarks Defects not found</p>		<p>Remarks Spare Key - Issue - Unexist</p>	

Inspector Notes

With Lto plate, with warranty booklet, with spare tire and jack, 1key, no tools