

General Information

Date & Time: 08, Jan, 2025 10:35

Make	Toyota	Model	Vios
YOM	2023	Mileage	37,420
Registration No.	NHI4291	Chassis No.	PA1B18F35P4205553
CC	1.3	Transmission	CVT
Fuel Type	Gas	Type of Body	Sedan
Colour	Blue		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	109.6	114	106	109
2	Boot Lid	102.3	108	94	105
3	Roof	93.3	98	94	90/92
4	Left Front Fender	93.3	92	90	98
5	Left Front Door	102.4	104	111	92
6	Center Panel Left				
7	Left Rear Door	97.4	96	95	101
8	Left Back Panel	96.2	99	93	96
9	Right Front Fender	90.8	95	89	89
10	Right Front Door	95.2	92	97	96
11	Center Panel Right				
12	Right Rear Door	100.1	108	100	92
13	Right Back Panel	97.8	102	96	96

Overall Evaluation :

A

Disclaimer

This Grading Report is intended to record the general appearance and condition of the interior, exterior & frame of the vehicle. This is not a detailed inspection report. This is issued on the date and time given herein and the company shall not be liable for the condition of the vehicle after this date and time. Any disputes regarding this report shall not be grounds for arbitration.

Interior Evaluation : B	Exterior Evaluation : B
 a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain	 A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap
Remarks (R) Front Floor Mat - Missing - Yes / (L) Front Floor Mat - Missing - Yes / Mat Other - Missing - Yes / Rear Seat - Grime - Medium / (R) Front Seat - Grime - Medium	Remarks Roof - Dent - Small / Trunk Hood, Rear Gate - Dent - Small / Front Bumper, Grille, Lamps - Dent - Medium / (R) Front Fender, Molding - Dent - Small
Frame Evaluation : A	Functional Evaluation : A
Remarks Defects not found	Remarks Reverse Camera - N/A - Yes / Spare Key - Issue - Unexist

Inspector Notes
no warranty booklet/ with spare tire jack and tools