

General Information

Date & Time: 20, Nov, 2025 10:08

Make	Toyota	Model	Vios
YOM	2025	Odo Meter Reading	25,139
Registration No.	NHS5039	Chassis No.	PA1B18F35R4264119
CC	1.3	Transmission	CVT
Fuel Type	Gas	Type of Body	Sedan
Colour	Silver		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	116.6	121	102	127
2	Boot Lid	106.6	100	111	109
3	Roof	105.4	100	112	100/110
4	Left Front Fender	104.6	108	102	104
5	Left Front Door	100.8	101	102	100
6	Center Panel Left				
7	Left Rear Door	103.1	103	95	111
8	Left Back Panel	107.6	110	108	105
9	Right Front Fender	102.6	102	103	103
10	Right Front Door	102.3	103	100	104
11	Center Panel Right				
12	Right Rear Door	108.0	107	101	116
13	Right Back Panel	107.0	101	106	114

Overall Evaluation :

C

Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

Interior Evaluation :	C	Exterior Evaluation :	E
			
<p>a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain</p>		<p>A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap</p>	
<p>Remarks Rear Seat - Grime - Medium / (R) Front Seat - Grime - Medium / (R) Front Trim - Grime - Medium / (L) Front Trim - Grime - Medium / (L) Front Seat - Grime - Medium / (L) Front Floor Mat - Cut, Crack - Medium / Ceiling - Grime - Small / Dashboard - Traces of Adhesive Tape - Yes / Console, Switchs, Vents - Worn, Scratch, Cut, Crack - Small</p>		<p>Remarks (R) Front Fender, Molding - Scratch & Dent - Large / Front Bumper, Grille, Lamps - Scratch - Large / Member (Bolted) - Dent - Yes / (R) Mirror - Crack - Damaged / (R) Front Door, Molding - Scratch - Small / (R) Rear Door, Molding - Scratch & Dent - Large / (R) Step, In-panel, Side Spoiler - Scratch & Dent - Large / (R) Rear Fender, Molding - Scratch & Dent - Small / Rear Bumper, Lamps, Panels - Scratch & Dent - Medium / (L) Rear Fender, Molding - Scratch - Small / (L) Rear Door, Molding - Scratch - Minimal / (L) Front Door, Molding - Scratch - Medium / (L) Front Fender, Molding - Scratch - Small / Bonnet, Headlight - Rust, Corrosion - Medium / Trunk Hood, Rear Gate - Scratch & Dent - Minimal / Roof - Scratch - Minimal</p>	
Frame Evaluation :	A	Functional Evaluation :	B
<p>Remarks Defects not found</p>		<p>Remarks Battery - Weak - Yes</p>	

Inspector Notes
with LTO plate/with spare tire/No spare key/with reverse camera/with warranty booklet/with jack No tools/rear seat issue/right side mirror issue