

General Information

Date & Time: 20, Nov, 2025 13:26

Make	Toyota	Model	Vios
YOM	2022	Odo Meter Reading	22,012
Registration No.	NFH9355	Chassis No.	PA1B18F34N4177919
CC	1.3	Transmission	CVT
Fuel Type	Gas	Type of Body	Sedan
Colour	Black		

Body / Panel Condition



#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	115.6	135	102	110
2	Boot Lid	113.3	112	112	116
3	Roof	107.1	116	100	100/113
4	Left Front Fender	108.6	103	112	111
5	Left Front Door	118.3	115	121	119
6	Center Panel Left				
7	Left Rear Door	120.3	122	130	109
8	Left Back Panel	116.0	123	113	112
9	Right Front Fender	105.6	111	113	93
10	Right Front Door	105.6	111	101	105
11	Center Panel Right				
12	Right Rear Door	105.6	102	103	112
13	Right Back Panel	104.0	106	93	113

Overall Evaluation :

C

Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

Interior Evaluation : C	Exterior Evaluation : D
<p>a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain</p>	<p>A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap</p>
<p>Remarks (R) Front Floor Mat - Grime - Medium / (L) Front Floor Mat - Grime - Medium / Console, Switchs, Vents - Worked - Minimal / (L) Front Trim - Grime - Medium / (L) Front Seat - Grime - Small / (R) Front Seat - Grime - Small / Rear Seat Head Rest - Worked - Small / Trunk Room - Worked - Minimal / Ceiling - Grime - Minimal / (R) Front Trim - Grime - Minimal / Glove Box - Worked - Minimal</p>	<p>Remarks Bonnet, Headlight - Repair mark - Yes / Bonnet, Headlight - Scratch - Small / (L) Front Fender, Molding - Scratch - Medium / (L) Front Door, Molding - Scratch - Medium / (L) Rear Door, Molding - Scratch - Medium / (L) Rear Fender, Molding - Scratch & Dent - Small / Trunk Hood, Rear Gate - Scratch & Dent - Small / Rear Bumper, Lamps, Panels - Scratch & Dent - Small / Roof - Scratch & Dent - Small / (R) Rear Door, Molding - Scratch - Small / (R) Front Door, Molding - Scratch - Small / (R) Front Fender, Molding - Scratch & Dent - Small / Front Bumper, Grille, Lamps - Scratch & Dent - Small / (L) Step, In-panel, Side Spoiler - Scratch & Dent - Minimal / (R) Step, In-panel, Side Spoiler - Scratch & Dent - Minimal / (R) Rear Fender, Molding - Scratch & Dent - Small</p>
Frame Evaluation : A	Functional Evaluation : B
<p>Remarks Defects not found</p>	<p>Remarks Battery - Weak - Yes / Reverse Camera - N/A - Yes</p>

<p>Inspector Notes</p>
<p>with LTO plate, with spare tire, with spare key, with jack & incomplete tools, with warranty & manual booklet, no reverse camera, scratches on taillight.</p>