

General Information

Date & Time: 24, Nov, 2025 10:15

Make	Toyota	Model	Vios
YOM	2022	Odo Meter Reading	49,862
Registration No.	NGQ3571	Chassis No.	PA1B18F39N6008077
CC	1.5	Transmission	CVT
Fuel Type	Gas	Type of Body	Sedan
Colour	Green		

Body / Panel Condition



#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	106.6	113	95	112
2	Boot Lid	103.8	104	100	108
3	Roof	93.6	105	92	89/89
4	Left Front Fender	95.8	93	97	98
5	Left Front Door	104.1	99	106	108
6	Center Panel Left				
7	Left Rear Door	104.1	110	108	95
8	Left Back Panel	107.3	115	102	105
9	Right Front Fender	91.4	92	91	91
10	Right Front Door	99.8	101	99	100
11	Center Panel Right				
12	Right Rear Door	99.1	106	96	96
13	Right Back Panel	106.6	103	103	114

Overall Evaluation :

C

Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

Interior Evaluation : C	Exterior Evaluation : C
<p>a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain</p>	<p>A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap</p>
<p>Remarks (L) Front Trim - Grime - Small / (L) Front Seat - Grime - Medium / (L) Front Floor Mat - Grime - Medium / (R) Front Seat - Grime - Small / Rear Seat - Grime - Medium / Console, Switches, Vents - Worn, Scratch, Cut, Crack - Small / Ceiling - Grime - Small</p>	<p>Remarks (L) Rear Fender, Molding - Dent - Small / (L) Rear Door, Molding - Scratch - Small / Rear Bumper, Lamps, Panels - Scratch & Dent - Small / Bonnet, Headlight - Scratch - Minimal / (R) Rear Door, Molding - Scratch - Minimal / Front Bumper, Grille, Lamps - Scratch - Minimal / (L) Front Fender, Molding - Scratch - Minimal / Trunk Hood, Rear Gate - Dent - Minimal / (R) Front Door, Molding - Scratch - Small / (R) Front Fender, Molding - Scratch - Small / (L) Front Door, Molding - Scratch - Small / (R) Rear Fender, Molding - Scratch - Small / Roof - Scratch - Small</p>
Frame Evaluation : A	Functional Evaluation : B
<p>Remarks Defects not found</p>	<p>Remarks Battery - Weak - Yes</p>

<p>Inspector Notes</p>
<p>with LTO plate/with spare tire/with spare key/with jack and incomplete tools/with warranty booklet/with reverse camera/rear seat issue/splatter of paint around the vehicle</p>