

General Information

Date & Time: 19, Nov, 2025 09:56

Make	Toyota	Model	Lite Ace
YOM	2024	Odo Meter Reading	24,267
Registration No.	DBO5864	Chassis No.	MHKU3FE10RK007391
CC	1.5	Transmission	M/T
Fuel Type	Gas	Type of Body	Dropside
Colour	White		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	59.0	57	65	55
2	Boot Lid	49.5	58	44	47
3	Roof	56.3	52	56	63/54
4	Left Front Fender	50.7	53	49	51
5	Left Front Door	50.9	51	55	47
6	Center Panel Left	65.7	73	56	68
7	Left Rear Door	41.4	40	40	44
8	Left Back Panel	44.8	44	46	45
9	Right Front Fender	57.3	60	53	58
10	Right Front Door	52.9	49	53	57
11	Center Panel Right	64.3	80	55	59
12	Right Rear Door	40.7	42	43	38
13	Right Back Panel	44.0	42	47	43

Overall Evaluation :

C

Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

Interior Evaluation : C	Exterior Evaluation : D
 <p>a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain</p>	 <p>A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap</p>
Remarks (L) Front Seat - Grime - Medium / (R) Front Seat - Grime - Medium / Ceiling - Grime - Small / (R) Front Trim - Grime - Medium / (L) Front Trim - Grime - Medium / Dashboard - Worn, Scratch, Cut, Crack - Small / Console, Switches, Vents - Worn, Scratch, Cut, Crack - Small	Remarks (L) Center Panel - Scratch & Dent - Minimal / (L) Front Fender, Molding - Scratch - Small / (R) Front Fender, Molding - Scratch - Minimal / Front Bumper, Grille, Lamps - Scratch - Small / (R) Center Panel - Scratch - Small / Rear Gate - Scratch - Small / Rear Bumper, Lamps, Panels - Dent - Small / Cargo Bed Floor - Scratch & Dent - Large / (L) Side Gate - Scratch - Medium / (R) Side Gate - Scratch - Small / Roof - Dent - Large / Cab Back Panel - Scratch - Small / (L) Mirror - Scratch - Minimal / (R) Mirror - Scratch - Minimal
Frame Evaluation : A	Functional Evaluation : B
Remarks Defects not found	Remarks Battery - Weak - Yes / Reverse Camera - N/A - Yes / Spare Key - Issue - Unexist

Inspector Notes
with LTO plate/with spare tire/No reverse camera/No spare key/No jack and tools/with warranty booklet/left and right front door traces of adhesive tape /left side tail light medium crack