

General Information

Date & Time: 18, Nov, 2025 13:16

Make	Mitsubishi	Model	Mirage
YOM	2021	Odo Meter Reading	24,935
Registration No.	GAV1288	Chassis No.	PAEA13RJMMMA021665
CC	1.2	Transmission	A/T
Fuel Type	Gas	Type of Body	Sedan
Colour	Gray		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	107.6	103	109	111
2	Boot Lid	107.0	103	115	103
3	Roof	95.1	101	96	92/91
4	Left Front Fender	110.0	113	106	111
5	Left Front Door	97.9	100	99	95
6	Center Panel Left				
7	Left Rear Door	94.6	96	95	93
8	Left Back Panel	102.3	111	110	86
9	Right Front Fender	121.0	142	108	113
10	Right Front Door	99.5	99	102	98
11	Center Panel Right				
12	Right Rear Door	94.8	91	94	100
13	Right Back Panel	100.6	89	101	112

Overall Evaluation :

B

Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

Interior Evaluation : A	Exterior Evaluation : D
 a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain	 A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap
Remarks (R) Front Floor Mat - Grime - Small / Ceiling - Grime - Small / (L) Front Floor Mat - Worked - Small	Remarks (R) Rear Door, Molding - Scratch & Dent - Small / (R) Front Door, Molding - Dent - Small / (R) Rear Fender, Molding - Scratch - Small / Rear Bumper, Lamps, Panels - Repair mark - Yes / Rear Bumper, Lamps, Panels - Crack, Gap - Large / Trunk Hood, Rear Gate - Scratch - Small / (L) Rear Fender, Molding - Scratch - Small / (L) Rear Door, Molding - Scratch & Dent - Medium / (L) Front Door, Molding - Scratch - Small / Bonnet, Headlight - Scratch & Dent - Small / (L) Front Fender, Molding - Scratch - Small / Front Bumper, Grille, Lamps - Scratch & Dent - Small / (R) Front Fender, Molding - Scratch - Minimal / (R) Mirror - Scratch - Small / Roof - Repair mark - Yes / Roof - Scratch - Small
Frame Evaluation : A	Functional Evaluation : B
Remarks Defects not found	Remarks Battery - Weak - Yes / Reverse Camera - N/A - Yes / Spare Key - Issue - Unexist

Inspector Notes

Without warranty booklet and tools. With spare tire,jack and leather seat cover. 1 key. With LTO plate.