

General Information

Date & Time: 09, Dec, 2025 19:32

Make	Suzuki	Model	S-Presso
YOM	2025	Odo Meter Reading	5,998
Registration No.	GBJ6593	Chassis No.	MA3FL61S0SA528460
CC	1.0	Transmission	A/T
Fuel Type	Gas	Type of Body	Hatchback
Colour	White		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	115.0	115	112	118
2	Boot Lid	103.8	103	111	98
3	Roof	115.5	118	114	114/116
4	Left Front Fender	105.0	110	101	104
5	Left Front Door	106.6	111	104	105
6	Center Panel Left				
7	Left Rear Door	111.3	115	111	108
8	Left Back Panel	124.0	120	122	130
9	Right Front Fender	104.3	104	104	105
10	Right Front Door	106.1	98	113	107
11	Center Panel Right				
12	Right Rear Door	105.0	97	110	108
13	Right Back Panel	120.3	124	111	126

Overall Evaluation :

B

Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

Interior Evaluation : B	Exterior Evaluation : C
 <p>a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain</p>	 <p>A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap</p>
<p>Remarks Ceiling - Grime - Small / (R) Front Floor Mat - Grime - Minimal / Mat Other - Grime - Small / Rear Seat - Grime - Small / (L) Front Floor Mat - Worked - Small</p>	<p>Remarks (R) Mirror - Scratch - Small / (R) Front Door, Molding - Scratch - Medium / (R) Rear Door, Molding - Scratch - Small / (L) Front Door, Molding - Scratch & Dent - Large / Trunk Hood, Rear Gate - Scratch - Minimal / Rear Bumper, Lamps, Panels - Scratch - Small / (L) Rear Door, Molding - Scratch - Minimal / (L) Front Fender, Molding - Scratch & Dent - Small / (L) Mirror - Scratch - Minimal / Front Bumper, Grille, Lamps - Scratch - Small</p>
Frame Evaluation : A	Functional Evaluation : B
<p>Remarks Defects not found</p>	<p>Remarks Retractable Mirror - Issue - Yes / Reverse Camera - N/A - Yes</p>

<p>Inspector Notes</p>
<p>Without warranty booklet and tools. With spare tire, jack and seat cover. 2 keys. No LTO plate.</p>