

General Information

Date & Time: 28, Nov, 2025 09:10

Make	Suzuki	Model	Carry
YOM	2023	Odo Meter Reading	15,719
Registration No.	GBA7993	Chassis No.	MHYDC61T2PJ214802
CC	1.5	Transmission	M/T
Fuel Type	Gas	Type of Body	Van
Colour	White		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	107.0	107	111	103
2	Boot Lid	139.6	150	153	116
3	Roof	103.1	112	110	96/94
4	Left Front Fender	113.6	117	103	121
5	Left Front Door	108.0	113	108	103
6	Center Panel Left	101.2	105	101	98
7	Left Rear Door				
8	Left Back Panel	127.3	112	148	122
9	Right Front Fender	102.0	109	110	87
10	Right Front Door	108.6	107	113	106
11	Center Panel Right	102.5	108	102	98
12	Right Rear Door				
13	Right Back Panel	144.0	103	194	135

Overall Evaluation :

C

Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

Interior Evaluation : C	Exterior Evaluation : D
 a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain	 A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap
Remarks Ceiling - Grime - Medium / Rear Seat - Grime - Large	Remarks (L) Center Panel - Scratch & Dent - Medium / (L) Front Door, Molding - Scratch - Small / (R) Front Fender, Molding - Scratch - Small / Front Bumper, Grille, Lamps - Scratch - Small / (R) Mirror - Scratch - Small / (R) Front Door, Molding - Scratch - Medium / (R) Center Panel - Scratch - Small / (R) Side Gate - Scratch - Small / Rear Bumper, Lamps, Panels - Scratch & Dent - Large / Rear Gate - Scratch - Small / (L) Side Gate - Scratch - Minimal / Roof - Scratch - Small / (R) Rear Corner Panel - Scratch - Small
Frame Evaluation : A	Functional Evaluation : A
Remarks Defects not found	Remarks Reverse Camera - N/A - Yes / Spare Key - Issue - Unexist

Inspector Notes

With warranty booklet and seat cover. Without spare tire, jack and tools. 1 key. With Temporary plate. LTO plate not installed.