

General Information

Date & Time: 05, Jan, 2026 15:27

Make	Toyota	Model	Vios
YOM	2023	Odo Meter Reading	140,261
Registration No.	GAS9410	Chassis No.	PA1B18F37N4194150
CC	1.3	Transmission	CVT
Fuel Type	Gas	Type of Body	Sedan
Colour	Silver		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	118.3	121	113	121
2	Boot Lid	116.0	111	117	120
3	Roof	99.1	106	96	95/100
4	Left Front Fender	101.2	104	103	97
5	Left Front Door	102.7	103	109	96
6	Center Panel Left				
7	Left Rear Door	105.3	107	105	104
8	Left Back Panel	105.3	112	101	103
9	Right Front Fender	111.6	109	112	114
10	Right Front Door	108.0	107	109	108
11	Center Panel Right				
12	Right Rear Door	109.3	106	110	112
13	Right Back Panel	113.3	113	111	116

Overall Evaluation :

C

Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

Interior Evaluation : B	Exterior Evaluation : E
 <p>a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain</p>	 <p>A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap</p>
<p>Remarks Dashboard - Traces of Adhesive Tape - Yes / Ceiling - Grime - Small / Overall Interior - Animal Hair - Yes / (R) Front Trim - Grime - Small / (L) Front Trim - Grime - Medium / (L) Front Floor Mat - Worked - Small</p>	<p>Remarks (R) Mirror - Scratch - Small / (R) Front Fender, Molding - Scratch - Small / (R) Front Door, Molding - Scratch & Dent - Large / (R) Rear Door, Molding - Scratch - Small / (R) Rear Fender, Molding - Scratch - Small / Trunk Hood, Rear Gate - Scratch & Dent - Medium / Rear Bumper, Lamps, Panels - Scratch & Dent - Large / (L) Rear Fender, Molding - Scratch - Small / (L) Rear Door, Molding - Scratch - Small / (L) Front Door, Molding - Scratch - Small / (L) Mirror - Scratch - Minimal / (L) Front Fender, Molding - Scratch - Medium / Front Bumper, Grille, Lamps - Scratch & Dent - Large / Bonnet, Headlight - Scratch - Small / Roof - Scratch - Small</p>
Frame Evaluation : A	Functional Evaluation : D
<p>Remarks Defects not found</p>	<p>Remarks Retractable Mirror - Issue - Yes / Power Steering - Issue - Yes / Battery - Weak - Yes / Reverse Camera - N/A - Yes / Spare Key - Issue - Unexist</p>

<p>Inspector Notes</p>
<p>Possible flooding. Retractable mirror switch issue. Cannot confirm spare tire and tools, cannot take pictures of trunk room and spare tire due of Trunk lever issue it cannot open the trunk door. Gap at front bumper. Scratches at tail light. With warranty booklet and seat cover. 1 key. With LTO plate.</p>