

General Information

Date & Time: 05, Dec, 2025 09:34

Make	Toyota	Model	Wigo
YOM	2025	Odo Meter Reading	6,844
Registration No.	GBJ7621	Chassis No.	MHKAA1BC7SJ036947
CC	1.0	Transmission	CVT
Fuel Type	Gas	Type of Body	Hatchback
Colour	Red		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	121.6	120	115	130
2	Boot Lid	104.3	101	106	106
3	Roof	99.7	103	93	104/99
4	Left Front Fender	98.7	100	98	98
5	Left Front Door	107.0	113	103	105
6	Center Panel Left				
7	Left Rear Door	104.6	109	102	103
8	Left Back Panel	99.6	100	101	98
9	Right Front Fender	96.1	92	96	100
10	Right Front Door	106.6	106	105	109
11	Center Panel Right				
12	Right Rear Door	111.0	112	111	110
13	Right Back Panel	102.3	104	101	102

Overall Evaluation :

B

Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

Interior Evaluation : A	Exterior Evaluation : D
 <p>a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain</p>	 <p>A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap</p>
<p>Remarks Ceiling - Grime - Small / (L) Front Floor Mat - Worked - Small</p>	<p>Remarks (R) Rear Door, Molding - Scratch - Small / (R) Front Door, Molding - Scratch - Minimal / (R) Rear Fender, Molding - Scratch - Medium / Rear Bumper, Lamps, Panels - Scratch - Small / (L) Rear Fender, Molding - Scratch - Minimal / (L) Rear Door, Molding - Scratch - Large / (L) Front Door, Molding - Scratch - Small / (L) Front Fender, Molding - Scratch - Small / Roof - Scratch - Minimal / Front Bumper, Grille, Lamps - Scratch & Dent - Large / (R) Front Fender, Molding - Scratch - Medium / (R) Mirror - Scratch - Minimal</p>
Frame Evaluation : A	Functional Evaluation : A
<p>Remarks Defects not found</p>	<p>Remarks Spare Key - Issue - Unexist</p>

<p>Inspector Notes</p>
<p>Without warranty booklet and tools. With spare tire, jack and sear cover. 1 key. With LTO plate.</p>