

## General Information

Date & Time: 05, Dec, 2025 10:19

<b>Make</b>	Toyota	<b>Model</b>	Vios
<b>YOM</b>	2024	<b>Odo Meter Reading</b>	25,438
<b>Registration No.</b>	HAH7232	<b>Chassis No.</b>	PA1B18F38R4244415
<b>CC</b>	1.3	<b>Transmission</b>	M/T
<b>Fuel Type</b>	Gas	<b>Type of Body</b>	Sedan
<b>Colour</b>	Silver		

## Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	115.0	118	109	118
2	Boot Lid	110.6	105	114	113
3	Roof	99.6	99	103	95/102
4	Left Front Fender	97.5	100	96	97
5	Left Front Door	99.0	101	99	98
6	Center Panel Left				
7	Left Rear Door	105.0	116	103	96
8	Left Back Panel	108.0	115	105	104
9	Right Front Fender	101.3	105	97	102
10	Right Front Door	100.6	100	100	102
11	Center Panel Right				
12	Right Rear Door	107.6	103	109	111
13	Right Back Panel	104.6	100	106	108

## Overall Evaluation :

**A**

### Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

<b>Interior Evaluation :</b> <span style="float: right; color: red; font-weight: bold;">A</span>	<b>Exterior Evaluation :</b> <span style="float: right; color: red; font-weight: bold;">C</span>
 <p><b>a</b> : Cut, Fray <b>d</b> : Loose, Deformed <b>k</b> : Animal Hair <b>s</b> : Smell <b>t</b> : Cigarette Burns <b>x</b> : Defective <b>y</b> : Stain</p>	 <p><b>A</b> : Scratch <b>AU</b> : Scratch &amp; Dent <b>B</b> : Modified <b>C</b> : Corrosion <b>G</b> : Stone chip <b>P</b> : Faded <b>S</b> : Rust <b>SC</b> : Rust &amp; Corrosion <b>U</b> : Dent <b>X</b> : Defective <b>Y</b> : Crack, Gap</p>
<p><b>Remarks</b> Ceiling - Grime - Small / (R) Front Floor Mat - Grime - Small / (R) Front Trim - Grime - Minimal / Mat Other - Grime - Minimal / (L) Front Trim - Grime - Small</p>	<p><b>Remarks</b> (R) Mirror - Scratch - Minimal / (R) Rear Door, Molding - Scratch - Minimal / (R) Front Door, Molding - Scratch - Small / Rear Bumper, Lamps, Panels - Scratch - Minimal / (L) Front Door, Molding - Scratch - Large / Roof - Dent - Small / Front Bumper, Grille, Lamps - Scratch &amp; Dent - Small</p>
<b>Frame Evaluation :</b> <span style="float: right; color: red; font-weight: bold;">A</span>	<b>Functional Evaluation :</b> <span style="float: right; color: red; font-weight: bold;">A</span>
<p><b>Remarks</b> Defects not found</p>	<p><b>Remarks</b> Defects not found</p>

<p><b>Inspector Notes</b></p>
<p>Without warranty booklet, tools, jack, and seat cover. With spare tire. 3 keys. With LTO plate.</p>