

General Information

Date & Time: 28, Nov, 2025 09:37

Make	Toyota	Model	Wigo
YOM	2023	Odo Meter Reading	35,512
Registration No.	GAP8130	Chassis No.	MHKA4DF5NJ077935
CC	1.0	Transmission	A/T
Fuel Type	Gas	Type of Body	Hatchback
Colour	Black		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	98.4	104	100	91
2	Boot Lid	100.4	95	105	101
3	Roof	89.8	93	89	95/83
4	Left Front Fender	97.4	95	102	96
5	Left Front Door	100.8	105	99	98
6	Center Panel Left				
7	Left Rear Door	97.8	102	99	93
8	Left Back Panel	96.3	93	105	91
9	Right Front Fender	99.4	100	100	98
10	Right Front Door	99.0	95	100	102
11	Center Panel Right				
12	Right Rear Door	97.2	101	96	94
13	Right Back Panel	100.9	94	99	110

Overall Evaluation :

B

Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

Interior Evaluation : A	Exterior Evaluation : E
 <p>a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain</p>	 <p>A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap</p>
<p>Remarks Rear Seat - Grime - Small / (R) Front Seat - Grime - Small / Ceiling - Grime - Small / Sunvisor, Sunglass Holder - Grime - Small</p>	<p>Remarks (R) Front Fender, Molding - Scratch & Dent - Medium / (R) Mirror - Scratch - Small / (R) Front Door, Molding - Scratch - Medium / (R) Rear Door, Molding - Scratch - Large / (R) Center Panel - Scratch - Small / (R) Rear Fender, Molding - Scratch - Small / Trunk Hood, Rear Gate - Scratch - Small / Rear Bumper, Lamps, Panels - Scratch - Small / (L) Rear Fender, Molding - Scratch - Minimal / (L) Rear Door, Molding - Scratch - Small / (L) Front Door, Molding - Scratch - Small / (L) Mirror - Scratch - Small / (L) Front Fender, Molding - Scratch - Small / Front Bumper, Grille, Lamps - Scratch & Dent - Medium / Roof - Scratch - Small</p>
Frame Evaluation : A	Functional Evaluation : A
<p>Remarks Defects not found</p>	<p>Remarks Spare Key - Issue - Unexist</p>

<p>Inspector Notes</p>
<p>Trunk floor missing. dent at left side mirror. With warranty booklet, spare tire, jack and tools. Incomplete seat cover. 1 key. Temporary plate.</p>