

General Information

Date & Time: 21, Nov, 2025 10:33

Make	Toyota	Model	Wigo
YOM	2021	Odo Meter Reading	49,996
Registration No.	KAG5568	Chassis No.	MHKA4DF5FMJ054806
CC	1.0	Transmission	A/T
Fuel Type	Gas	Type of Body	Hatchback
Colour	White		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	84.3	88	90	75
2	Boot Lid	88.0	87	89	89
3	Roof	64.7	61	72	63/63
4	Left Front Fender	124.6	123	123	128
5	Left Front Door	135.0	134	136	135
6	Center Panel Left				
7	Left Rear Door	129.3	152	113	123
8	Left Back Panel	108.7	122	117	87
9	Right Front Fender	83.4	80	85	86
10	Right Front Door	86.6	89	91	80
11	Center Panel Right				
12	Right Rear Door	87.3	87	80	94
13	Right Back Panel	84.5	81	80	92

Overall Evaluation :

C

Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

Interior Evaluation : B	Exterior Evaluation : D
 a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain	 A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap
Remarks Ceiling - Grime - Small / (R) Front Seat - Grime - Medium / Rear Seat - Grime - Medium / (L) Front Seat - Grime - Small	Remarks (R) Mirror - Scratch - Small / (R) Front Door, Molding - Scratch - Minimal / (R) Rear Fender, Molding - Dent - Medium / (R) Rear Door, Molding - Scratch - Small / (R) Step, In-panel, Side Spoiler - Scratch - Small / Rear Bumper, Lamps, Panels - Scratch - Medium / (L) Rear Fender, Molding - Scratch - Small / (L) Rear Door, Molding - Scratch - Small / (L) Front Door, Molding - Scratch - Small / (L) Mirror - Scratch - Small / Front Bumper, Grille, Lamps - Repair mark - Yes / (L) Front Fender, Molding - Scratch - Small / Front Bumper, Grille, Lamps - Scratch - Large / Bonnet, Headlight - Scratch - Minimal / (R) Front Fender, Molding - Scratch & Dent - Minimal / Roof - Scratch - Small
Frame Evaluation : A	Functional Evaluation : B
Remarks Defects not found	Remarks Battery - Weak - Yes / Spare Key - Issue - Unexist

Inspector Notes

Without warranty booklet, tools, and seat cover. With spare tire and jack. 1 key. With LTO plate.