

General Information

Date & Time: 20, Nov, 2025 16:01

Make	Toyota	Model	Vios
YOM	2024	Odo Meter Reading	16,155
Registration No.	NHQ6434	Chassis No.	PA1B18F36R4252304
CC	1.3	Transmission	CVT
Fuel Type	Gas	Type of Body	Sedan
Colour	Red		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	123.6	125	118	128
2	Boot Lid	113.3	112	111	117
3	Roof	107.2	119	101	109/100
4	Left Front Fender	104.3	108	100	105
5	Left Front Door	111.0	111	111	111
6	Center Panel Left				
7	Left Rear Door	116.6	125	114	111
8	Left Back Panel	115.3	117	114	115
9	Right Front Fender	104.6	106	105	103
10	Right Front Door	109.6	110	109	110
11	Center Panel Right				
12	Right Rear Door	116.0	110	110	128
13	Right Back Panel	109.0	109	109	109

Overall Evaluation :

C

Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

Interior Evaluation :	B	Exterior Evaluation :	E
			
<p>a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain</p>		<p>A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap</p>	
<p>Remarks (L) Front Floor Mat - Worked - Small / (L) Front Trim - Worked - Small / (R) Front Trim - Worked - Small / Ceiling - Grime - Small / Overall Interior - Animal Hair - Yes / Overall Interior - Smell - Yes / (R) Front Seat - Grime - Small / (L) Front Seat - Grime - Small</p>		<p>Remarks Trunk Hood, Rear Gate - Repair Traces - Yes / (L) Front Fender, Molding - Repair mark - Yes / (R) Front Fender, Molding - Repair mark - Yes / Bonnet, Headlight - Repair mark - Yes / Trunk Hood, Rear Gate - Repair mark - Yes / Member (Bolted) - Dent - Yes / Bonnet, Headlight - Scratch & Dent - Small / (R) Mirror - Scratch - Minimal / (R) Front Fender, Molding - Scratch - Minimal / (R) Front Door, Molding - Scratch & Dent - Small / (R) Rear Door, Molding - Scratch - Small / (R) Step, In-panel, Side Spoiler - Scratch & Dent - Small / (R) Rear Fender, Molding - Scratch - Minimal / Front Bumper, Grille, Lamps - Scratch - Small / Trunk Hood, Rear Gate - Scratch & Dent - Small / Roof - Scratch & Dent - Small / (L) Front Door, Molding - Scratch - Small / (L) Step, In-panel, Side Spoiler - Scratch & Dent - Small / (L) Front Fender, Molding - Scratch & Dent - Small / (L) Mirror - Scratch - Minimal / (L) Rear Door, Molding - Scratch - Medium / (L) Rear Fender, Molding - Scratch - Medium</p>	
Frame Evaluation :	C	Functional Evaluation :	A
<p>Remarks Front Cross Member Support - Condition of Welding ? - Yes / Right Front Inside Panel (Front Side) - Traces of Bending, or Marks of Panel Repair ? - Yes / Left Front Inside Panel (Front Side) - Traces of Bending, or Marks of Panel Repair ? - Yes</p>		<p>Remarks Spare Key - Issue - Unexist</p>	

Inspector Notes
With LTO plate and warranty booklet, Incomplete Tools, No Sparetire and Jack, No Spare key, Scratch headlight and tail light, Worn Tires, foul smell.