

General Information

Date & Time: 21, Nov, 2025 13:37

Make	Toyota	Model	Wigo
YOM	2015	Odo Meter Reading	142,703
Registration No.	AAH3148	Chassis No.	MHKA4DF3F0J004071
CC	1.0	Transmission	A/T
Fuel Type	Gas	Type of Body	Hatchback
Colour	Black		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	203.6	239	197	175
2	Boot Lid	92.7	86	90	102
3	Roof	65.3	59	81	61/61
4	Left Front Fender	227.0	250	254	177
5	Left Front Door	101.6	101	103	101
6	Center Panel Left				
7	Left Rear Door	103.6	105	102	104
8	Left Back Panel	129.0	137	123	127
9	Right Front Fender	360.6	397	334	351
10	Right Front Door	97.5	97	90	106
11	Center Panel Right				
12	Right Rear Door	96.8	101	97	92
13	Right Back Panel	272.3	341	266	210

Overall Evaluation :

D

Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

Interior Evaluation : C	Exterior Evaluation : E
 <p>a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain</p>	 <p>A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap</p>
<p>Remarks Ceiling - Grime - Small / Sunvisor, Sunglass Holder - Grime - Small / (R) Front Seat - Grime - Medium / Rear Seat - Grime - Large / (L) Front Trim - Worked - Small / (L) Rear Trim - Worked - Small / (R) Front Trim - Worked - Small / (R) Rear Trim - Worked - Small / Overall Interior - Worn as per age - Yes / Overall Interior - Smell - Yes / Trunk Room - Loose, Deformed - Large / (L) Front Seat - Grime - Small</p>	<p>Remarks (R) Front Door - Repair Traces - Yes / (R) Step - Repair Traces - Yes / (R) Front Fender - Repair Traces - Yes / Bonnet - Repair Traces - Yes / (L) Front Fender - Repair Traces - Yes / (L) Step - Repair Traces - Yes / Trunk Hood, Rear Gate - Repair Traces - Yes / (R) Rear Fender - Repair Traces - Yes / (R) Rear Door - Repair Traces - Yes / Roof - Repair Traces - Yes / (R) Mirror - Scratch - Small / (R) Front Door, Molding - Scratch & Dent - Small / (R) Rear Door, Molding - Scratch & Dent - Large / (R) Rear Fender, Molding - Scratch - Large / (R) Step, In-panel, Side Spoiler - Scratch - Small / Trunk Hood, Rear Gate - Scratch - Large / Rear Bumper, Lamps, Panels - Scratch & Dent - Large / (L) Rear Fender, Molding - Scratch - Large / (L) Rear Door, Molding - Scratch & Dent - Large / (L) Front Door, Molding - Scratch - Medium / (L) Mirror - Scratch - Small / (L) Front Fender, Molding - Scratch - Small / (L) Step, In-panel, Side Spoiler - Scratch - Small / Overall Exterior - Faded(Color, Gloss) - Yes / Overall Exterior - Worn as per age - Yes / Front Bumper, Grille, Lamps - Repair mark - Yes / Member (Bolted) - Dent - Yes / Front Bumper, Grille, Lamps - Scratch & Dent - Large / (R) Front Fender, Molding - Scratch - Medium / Bonnet, Headlight - Scratch - Small</p>
Frame Evaluation : A	Functional Evaluation : C
<p>Remarks Defects not found</p>	<p>Remarks Air Conditioner - Function - Weak / Battery - Weak - Yes / Audio, Radio - Issue - Yes / Reverse Camera - N/A - Yes / Spare Key - Issue - Unexist</p>

<p>Inspector Notes</p>
<p>Possible flooding. Trunk floor issue. Without jack, tools and seat cover. With warranty booklet and spare tire. 1 key. With LTO plate.</p>