

General Information

Date & Time: 20, Nov, 2025 16:01

Make	Mitsubishi	Model	Mirage
YOM	2023	Odo Meter Reading	22,612
Registration No.	NHL1956	Chassis No.	PAEA13TJPPA010885
CC	1.2	Transmission	A/T
Fuel Type	Gas	Type of Body	Sedan
Colour	Red		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	120.3	118	125	118
2	Boot Lid	107.5	99	120	104
3	Roof	103.0	99	109	101/103
4	Left Front Fender	106.0	109	106	103
5	Left Front Door	109.3	111	107	110
6	Center Panel Left				
7	Left Rear Door	104.3	108	104	101
8	Left Back Panel	117.3	123	116	113
9	Right Front Fender	106.5	98	105	117
10	Right Front Door	111.0	115	105	113
11	Center Panel Right				
12	Right Rear Door	105.6	104	103	110
13	Right Back Panel	111.3	107	114	113

Overall Evaluation :

A

Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

Interior Evaluation : A	Exterior Evaluation : C
 <p>a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain</p>	 <p>A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap</p>
<p>Remarks Ceiling - Grime - Small / (R) Front Floor Mat - Grime - Small / Rear Seat - Grime - Small / (L) Front Floor Mat - Worked - Small</p>	<p>Remarks (L) Rear Fender, Molding - Scratch - Small / (L) Mirror - Scratch - Small / (L) Rear Door, Molding - Scratch - Small / (L) Front Door, Molding - Scratch - Minimal / Bonnet, Headlight - Scratch - Minimal / Front Bumper, Grille, Lamps - Scratch & Dent - Small / (R) Mirror - Scratch - Small / (R) Front Fender, Molding - Scratch - Minimal / (R) Front Door, Molding - Scratch - Small / (R) Rear Door, Molding - Scratch - Small / (R) Rear Fender, Molding - Scratch - Small / Rear Bumper, Lamps, Panels - Scratch & Dent - Small / Roof - Dent - Small</p>
Frame Evaluation : A	Functional Evaluation : A
<p>Remarks Defects not found</p>	<p>Remarks Reverse Camera - N/A - Yes / Spare Key - Issue - Unexist</p>

<p>Inspector Notes</p>
<p>Without warranty booklwt and tools. With spare tire,jack and seat cover. 1 key. Temporary plate.</p>